










Area	Location	Asset Type	Defect / Repair Description	Timeframe	Representative Photo
External (Office and Carpark)	External	Building External, Fencing	Impact damaged fencing. Replace post and repair fencing (5 Lin.m).	1-2 years	 
External (Office and Carpark)	External	Building External, Smoking Area Structure	Minor surface corrosion of flooring and seating structural elements in smoking structure. Treat corrosion.	12 months	 
External (Office and Carpark)	External	Building External, Paving	Cracked and uneven pavers near rear toilets presents a trip hazard. Rectify.	12 months	 
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months	 

Area	Location	Asset Type	Defect / Repair Description	Timeframe	Representative Photo	
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months		
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months		
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months		
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months		

Area	Location	Asset Type	Defect / Repair Description	Timeframe	Representative Photo
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months	 
External (Yard)	External	Building External, Bollards	2 bollards have come loose, retighten. Remove deteriorated grout around base.	6 months	 
External (Yard)	External	Building External, Drainage Grates	Concrete handstand around drain grate has deteriorated. Need to replace.	1-2 years	 
External (Yard)	External	Building External, Asphalt	Asphalt between rail tracks is deteriorating. Localised repair required. Likely due to drainage pit structure shrinking below.	1-2 years	 

Area	Location	Asset Type	Defect / Repair Description	Timeframe	Representative Photo
Office 2 (Ground Floor)	Office Building	Electrical, Light Fittings	Replace 1 x light bulb.	6 months	
Main Area	Office Building	Building (Internal), Internal Wall	Wear and chipping of wall paint. Repaint walls.	12 months	 
Guard Room	Office Building	Building (Internal), Internal Wall	Significant wear and chipping of wall paint, Sand and repaint.	12 months	 
Yard Shed	Office Building	Electrical, Light Fittings	Replace 1 x light bulb.	6 months	 

Area	Location	Asset Type	Defect / Repair Description	Timeframe	Representative Photo
Male Toilet (Rear)	Office Building	Building (Internal), Internal Wall	Sand and repaint walls in toilet room.	12 months	
Female Toilet (Rear)	Office Building	Building (Internal), Internal Wall	Wall paint bubbling, sand back and repaint.	12 months	