

Jeewan Deep Batta.

Govt. of India Approved
Insurance Surveyor & Loss Assessor
Valuer and Investigator
Licence No : SLA - 7777
Valid Upto :26/10/2027

Office :

387, old city, Kotkapura-151204
Email- jd.batta@rediffmail.com
web: www.claimhub.com,www.motorclaim.in
Mob- +91-9814035162
jd.batta8810@gmail.com

PRIVATE AND CONFIDENTIAL
MOTOR FINAL SURVEY REPORT
VEHICLE NO. PB 04AG 2326

Ref. No. : JDB/1336

Date : 16/12/2025

This report is issued by me/us as licensed surveyor (s) without prejudice, in respect of cause, nature and extent of loss/damage and subject to the terms and conditions of Insurance policy.

Policy Number	: 2004033125P100647622	Claim No.	:
Policy Period	: 11/04/2025 - 10/04/2026	I.D.V.	: 935000

- | | |
|----------------|--|
| 1. Insurance | : United India Insurance Co. Ltd.
D.O./Br. : 200403
BO Mansa,, |
| 2. Insured | : M/s WAHEGURU TOURS AND TRAVELS
GF, Shop no. 02, PO: Moranwali, Near BSNL Office, Kaler,
Faridkot |
| 3. H.P.A. With | : SK Finance Ltd |

- | | | |
|----|----------------------------|---------------------------------|
| 4 | Vehicle Particulars | : RC Verified & Found In Order. |
| a) | Registration No. | : PB 04AG 2326 |
| b) | Date Of Registration | : 08/07/2024 |
| c) | Chassis No. | : 29758 |
| d) | Engine No. | : 51253 |
| e) | Make/Model | : Mahindra Bolero/2024 |
| f) | Type of Body | : Hard top |
| g) | Class of Vehicle | : MOTOR CAB |
| h) | Pre-accident Condition | : GOOD |
| I) | Registered Laden Weight | : 2220 Kg |
| j) | Unladen Weight | : 1570 Kg |
| k) | Fitness Cert. No. | : -- |
| | Valid upto | : 07/07/2026 |
| l) | Permit No. | : PB2024-CC-2979A |
| | Valid upto | : 01/08/2029 |
| m) | Type of permit | : Contract Carriage Permit |
| n) | Route/Area of operation | : Punjab State Only |
| o) | Tax paid upto | : 31/03/2026 |
| p) | Mileage | : 60881 Kms |
| q) | Colour | : D White |
| r) | CC | : 1493 cc |

- 5 Driver's Particulars** : DL Verified & Found In Order.
- a) Name of Driver : Mr SURINDER SINGH
- b) M.D.L. No. : PB04 20061884218
- Date of issue : 26/08/2025
- Valid upto : 25/08/2030
- c) Issuing authority : Faridkot
- d) Type of License : TRAILER/MCWG/LMV/TRANS
- e) Badge No. : NA

- a) Date & Time of Accident/Theft : 16/11/2025, 5:30 PM
- b) Place of Accident/Theft : Faridkot
- c) Place of Survey : M/S Dada Motors, Moga.
- d) Date of Allotment of Survey : 17/12/2025
- e) Date of Survey :
- f) Date of the Receipt of Spot Survey Report : NA
- g) Was Accident Reported To Police : NA
- h) Details Of Third Party Loss : NA

- 6 Cause And Nature of Accident (Description of Accident as stated in the claim from)** : It was stated hat while the car was moving on the under construction road, a stone came from nowhere & hit with the windscreen due to which driver got confused & vehicle also brushed a boulder on right side, resulting in damages
- 8 a. Particulars of report made to Police : NA
- 8 b) Any Other Coments : NA

In compliance to advices from your office the undersigned inspected the said vehicle & after photonapping & verifying the documents, all the visual damages were noted down. The undersigned again visited the repairer during repairs as well as after completion of repairs & only then the detailed estimate produced was scurntised & loss was assessed as under:

ASSESSMENT OF LOSS

LABOUR CHARGES

SR. No.	PARTICULARS OF LABOUR CHARGES	ESTIMATED	Assessed				GST%
			Opening/ Fitting	Cutting/ Welding	Denting	Painting	
1.	Labour As Allowed Under:	36650.00		0.00	0.00	0.00	
2.	Wind Shield Glass		650.00	0.00	0.00	0.00	
3.	Body Foot Step Side RH		260.00	0.00	0.00	0.00	
	Total Before Discount	36,650.00	910.00	0.00	0.00	0.00	
	Disc. Lab 0.00 % Paint 0.00 %		0.00	0.00	0.00	0.00	
	Total After Discount		910.00	0.00	0.00	0.00	
	GST	6,597.00	163.80	0.00	0.00	0.00	

	Grand Total	43,247.00	1,073.80	0.00	0.00	0.00
--	--------------------	------------------	-----------------	-------------	-------------	-------------

LABOUR TOTAL 1,073.80

SPARE PARTS

SL. No.	Name of Damaged Parts Which Are Assessed New	Estimated	Assessed				GST %
			Glass Parts Nill Dep	Metal Parts 0 % Dep	Fibber 30% Dep.	Rubber/Plastic 50% Dep.	
1.	Wind Shield Glass Beading	1,264.41					18.00
2.	Mirror Assy Rear View RH	527.97					18.00
3.	Glass Wind Shield Frt	2,881.36	2,881.36				18.00
4.	Panel Assy Bumper Frt	3,977.12					18.00
5.	Wheel Arch LH	132.20					18.00
6.	Cladding Assy RR Wheel Arch	1,250.00					18.00
7.	Foot Step Assy LH	3,627.12				3,627.12	18.00
8.	Cladding Assy Frt Wheel Arch RH	1,044.07					18.00
9.	Decal Side RH 3	433.90					18.00
10.	Decal Side RH 4	271.19					18.00
11.	Foot Step Assy RH	3,627.12					18.00
	Total Before GST	19,036.46	2,881.36	0.00	0.00	3,627.12	
	Add GST	3,426.56	518.64	0.00	0.00	652.88	
	Grand Total	22,463.02	3,400.00	0.00	0.00	4,280.00	
	Less Depreciation			0.00	0.00	0.00	
	Net Total	22,463.02	3,400.00	0.00	0.00	4,280.00	

SPARE PARTS TOTAL 7,680.01

NOTE :- The other spare parts proposed by the repairers were disallowed.

SUMMARY OF ASSESSMENT		Estimated	Assessed
Total Labour Charge	Rs.	43247.00	1073.80
Total Cost of Parts	Rs.	22,463.02	7,680.01
Total	Rs.	65,710.02	8,753.81
Less Excess	Rs.		500.00
Less Salvage Value	Rs.		107

NET LIABILITY

Rs.

65,710.02

8,146.81

Rupees Eight Thousand One Hundred Forty-Six And Eighty-One Paise Only

GST Summary - LABOUR CHARGES

TAX Percentage	Taxable Amt.	CGST	SGST	IGST	Total Amount
18.00	910.00	81.90	81.90	0.00	1,073.80
	910.00	81.90	81.90	0.00	1,073.80

GST Summary - SPARE PARTS

TAX Percentage	Taxable Amt.	CGST	SGST	IGST	Total Amount
18.00	6,508.48	585.76	585.76	0.00	7,680.01
	6,508.48	585.76	585.76	0.00	7,680.01

Remark :

We discussed the estimate in detail and assessed the loss on merit allowing reasonable labour charges and essential replacements.

"LIMITATIONS AS TO USE" CLAUSE have been duly complied with - Refer Claim form duly Filled by the insured.

The "DRIVER'S "CLAUSE have been duly complied with --Refer enclosed Driving Licence.

Re-inspection: I have re-inspected the captioned vehicle & have found that the repairs / or & replacements made there in were strictly followed as per our final survey report. I have also taken a few necessary photographs of the same along with the salvage parts. The vehicle re-inspected was found to be in road worthy condition at the time of my survey. As per the request of the insurer's we have also conducted the salvage destruction process during our re-inspection & also we have snapped a couple of photographs of the destructed salvage along with the vehicle for the verification of the same.

Recommendation:- We inspected the damage conforming to the nature of accident & is recommended for approval..

The claim amount may be disbursed in favour of insured.

The report is issued without prejudice subject to terms & conditions of the policy.

ISSUED WITHOUT PREJUDICE

Jeewan Deep Batta



Surveyor & Loss Assessor