

# East Victoria Street Surprises , carousel spec

A numbered, swipeable photo carousel about East Victoria Street, Indiana: real surprises on the property when the CPM team took over. "Surprise" is used deliberately in place of the earlier "things wrong" framing: a surprise does not have to be a problem, it can be any unexpected real detail, which is a wider and more honest net to work from than a defects list. This is the companion still-photo post to the separate portfolio montage reel built the same day, and is built from the same standing rule as every other piece of Shavit content: every caption traces to either something plainly visible in a real photo, or the one fact already confirmed by a dictated meeting transcript. All nineteen real photos from this property's Drive folder have been downloaded and individually viewed for this spec. Four support a fully written, confirmed caption: a damaged exterior window, a bent fence panel, an octagonal accent window on the gable end, and the basement's prior use. A fifth candidate, a closer photo of the same basement window, was cut per Jake's note for reading as redundant with the exterior window item once both sat in the same short carousel. That is four confirmed items, not a padded seven or any other round number chosen in advance. The hook slide states the number honestly as four. The carousel closes on two separate beats rather than one, a plain proof-of-work photo followed by a text-only title card, split apart per Jake's note.

6 slides · **5 real photos, no open slots**

4 confirmed surprises · **0 unconfirmed**

Format: **swipeable photo carousel**, not a reel

No people visible in selected photos · **de-identify check clear**

Status: **draft, awaiting Shavit review**

**UPDATED**, rev 3

## REVISION LOG, NEWEST FIRST

- **rev 7 · 2026-07-22**, Jake picked Option A for the closing title card. Marked final on slide 7, open-items checklist updated to reflect the closer is now decided, not open. Also fixed a leftover orphaned div tag from the rev 6 edit that had thrown off the annotation click targets.
- **rev 6 · 2026-07-22**, cut the standalone renovation-progress photo per Jake's note (he did not like it and questioned whether it was needed); the closing title card now uses a real photo of the house (the same front-exterior shot from the hook slide) as its background instead of a flat dark panel, with a scrim behind the text for legibility. Down to 6 slides total.
- **rev 5 · 2026-07-22**, restored the caption-overlay treatment on the renovation photo (slide 7) per Jake's follow-up note, it had been left bare in rev 4. Caption states only what is visible: fresh paint, protected floors and windows.

- **rev 4 · 2026-07-22**, per Jake's annotations: cut item 5 (the closer basement-window photo) for reading as redundant with item 1's window, dropping the confirmed count from five to four; changed "Shavit's team" to "the CPM team" in the basement caption; reworded the basement-window item to say the wood frame was rotten instead of repeating "cracked glass" from item 1; and split the closing slide into two separate beats, a plain renovation photo with no caption and a text-only title card carrying the three tagline options, instead of one combined slide. Confirmed "Live with us. Work with us." is the standing closing tagline across this project's reels.
- **rev 3 · 2026-07-22**, every photo now shows a mockup of the caption burned directly onto the image (uppercase Inter, white type, a short brass rule above the text, dark bottom scrim for legibility), matching this project's documented brand tokens, instead of only describing the on-screen text in a separate box below the photo. This is a best-effort approximation of the caption treatment referenced from the prior Howder review, not a pixel-exact match, annotate any slide if the type size, weight, or placement is off from what was actually agreed on before. The plain-text box under each photo is kept as the spec reference copy, the mockup above it is what it should actually look like. The closing slide now shows all three caption options rendered on the photo side by side instead of only as text, so the choice between them can be judged visually, not just read. No property or photo swap was made this revision, Jake confirmed the current material is acceptable to proceed with as flagged.
- **rev 2 · 2026-07-22**, per Jake's annotations: expanded from three confirmed items to five, reframed the whole concept from "things found/wrong" to "surprises," and rewrote the closing slide as three distinct options for Jake to pick from instead of one unilateral swap. To reach five honestly, all thirteen previously unreviewed photos from the property's nineteen-file Drive folder were downloaded and individually inspected. Two new confirmable items turned up: an octagonal accent window on the gable end, and a basement window at the foundation with cracked glass and a rotted frame, a stronger, more specific real photo for the basement item than the wide gable shot used before. Two of the newly reviewed photos turned out to already be in use in the sibling portfolio montage reel (the new HVAC unit and mulch bed exterior, and a backyard shed shot with a person visible shoveling snow) and were excluded here on the standing no-overlap-with-the-reel rule; the person-visible photo would also have failed the de-identify check on its own. Two more newly reviewed photos plainly show the property's house number on a porch placard and were excluded outright since street numbers are never used in this project. The previously open, unconfirmed garage-fence-debris slide is cut entirely, superseded by the two new confirmed items.
- **rev 1 · 2026-07-22**, initial draft. All photos downloaded from the confirmed Drive file ID list, opened and visually inspected before any caption was written. Two of the nineteen file IDs already used in today's separate portfolio montage reel were intentionally skipped so the two companion posts do not repeat the same stills.

| # | SLIDE                                    | PHOTO STATUS             | ON-SCREEN TEXT, SHORT                              |
|---|------------------------------------------|--------------------------|----------------------------------------------------|
| 1 | Hook / cover                             | real photo               | "4 surprises we found when we got the keys."       |
| 2 | Item 1, exterior window                  | real photo               | Cracked wood window frame                          |
| 3 | Item 2, rear fence                       | real photo               | Bent fence panel, wood board wedged in             |
| 4 | Item 3, gable window                     | real photo               | Octagonal accent window, gable end                 |
| 5 | Item 4, basement                         | real photo               | Basement's confirmed prior use, CPM team took over |
| 6 | Closing title card<br><div>UPDATED</div> | real photo<br>background | Tagline, 3 options                                 |

Two candidates were cut this round rather than defended: the closer basement-window shot (redundant with item 1) and the standalone renovation-progress photo (Jake did not like it and it was not earning its own slide). See their "removed" notes in the slide list below for the full reasoning.

Numbering logic: the hook slide promises exactly four surprises, and exactly four numbered items follow it, each one already confirmed either by what is visible in its photo or by the transcript. The item that used to run fifth, a closer shot of the same basement window, was cut per Jake's note since it read as redundant with item 1's window once both sat in the same short carousel, rather than force a fifth item just to hit a round number. The carousel now closes on two separate beats instead of one: a plain proof-of-work photo, then a text-only title card, split apart per Jake's note rather than combined into a single slide. The octagonal gable window is placed third deliberately, as the one item in the set that is a neutral, even pleasant surprise rather than a problem, demonstrating the broader "surprise" framing rather than a disguised defects list.

SLIDES

1. Hook / cover

real photo

not part of the count

UPDATED, rev 2

Establishing exterior shot of the property as it stood in December 2025, before any renovation work shown later in this same Drive folder. Snow on the ground, original vinyl siding. This slide states the carousel's premise and the real number of confirmed surprises that follow, reframed from an earlier "things found" draft to "surprises," a wording that covers both the problems and the neutral or pleasant finds in the same set.



**4 SURPRISES WE FOUND WHEN WE  
GOT THE KEYS.**  
EAST VICTORIA STREET, INDIANA.

FRONT EXTERIOR, SNOW

REAL

#### ON-SCREEN TEXT

4 surprises we found when we got the keys.  
East Victoria Street, Indiana.

#### PRODUCTION NOTE

Photo shows the front of the house, olive green vinyl siding, snow on the ground and covered porch, shot December 2025. This is the same visit that produced most of the item slides below, so it accurately represents condition at intake, not a staged or later shot. No caption claims anything is wrong with the house itself here, this slide only sets up the count that follows.

## 2. Item 1, exterior window

real photo

fully confirmed

Close-up of an exterior window. The wood muntins dividing the panes are visibly cracked and split in multiple places, and the white paint is peeling and flaking at several of those joints.



### 1. CRACKED WOOD WINDOW FRAME, EXTERIOR.

CRACKED WINDOW FRAME

REAL

#### ON-SCREEN TEXT

1. Cracked wood window frame, exterior.

#### PRODUCTION NOTE


Caption states only what the photo shows: cracked wood muntins and peeling paint on one exterior window. No claim is made about how many windows on the property are in this condition, whether it has been repaired since, or what caused it. If Shavit knows this was a single window or a house-wide issue, that context can be added to the caption later.

### 3. Item 2, rear fence

real photo

fully confirmed

Rear yard, beside the detached garage. The chain link fence's top rail is visibly bent, and a wood board is wedged into the fencing at ground level.



**2. BENT CHAIN LINK FENCE, WOOD BOARD WEDGED INTO THE FENCING, REAR YARD.**

BENT FENCE, WOOD BOARD

REAL

#### ON-SCREEN TEXT

2. Bent chain link fence, wood board wedged into the fencing, rear yard.

#### PRODUCTION NOTE

Same December 2025 visit as the window and basement window slides. Caption describes only what is visibly true: a bent top rail and a wood board caught in the fencing, no claim about whether the fence has since been repaired or replaced.


## 4. Item 3, gable window

real photo

fully confirmed

NEW, rev 2

Side gable end of the house, olive green siding, snow on the roofline. An octagonal accent window with white trim sits in the middle of the siding, a decorative shape that is easy to miss from the street-facing angle used in the hook photo. This photo was one of the thirteen previously unreviewed files from the property's Drive folder, downloaded and viewed for the first time in this revision.



### 3. OCTAGONAL WINDOW, GABLE END.

OCTAGONAL GABLE WINDOW

REAL

#### ON-SCREEN TEXT

3. Octagonal window, gable end.

#### PRODUCTION NOTE

Caption states only what the photo shows: a real octagonal window on the gable end. No claim is made about when it was installed or why. This is the one deliberately neutral, non-problem surprise in the set, placed third to demonstrate the "surprise" reframe rather than let all four items read as a defects list.

## 5. Item 4, basement

real photo

confirmed by transcript

UPDATED, rev 2

This is the one confirmed fact about this property's history, sourced from a real dictated meeting transcript, not from anything visible in a photo. No basement interior photo exists in the Drive folder for this property, so the exterior foundation and basement window are used to ground the slide in a real image of the actual house, the same honest pairing already used in today's companion reel spec for this same fact.



**4. BASEMENT WAS A DOG BREEDING  
OPERATION BEFORE PURCHASE.**  
PRIOR TENANTS WERE EVICTED BEFORE  
THE CPM TEAM TOOK OVER.

FOUNDATION, BASEMENT WINDOW

REAL

#### ON-SCREEN TEXT

4. Basement was a dog breeding operation before purchase.  
Prior tenants were evicted before the CPM team took over.

#### PRODUCTION NOTE

Photo shows the exterior foundation wall and a basement-level window, it does not show the basement's interior or the breeding operation itself, no such photo exists to show. The caption states a confirmed fact from the transcript, the photo grounds it in a real image of the actual foundation rather than an unrelated stock or generic shot. This item now leads directly into the next slide, a closer photo of an actual basement window found elsewhere in the folder.

### Item 5, basement window — cut

REMOVED, rev 4

Removed per Jake's note: this slide's closer shot of the same basement window was too close to slide 2's window-frame item to justify its own numbered beat once both were sitting in the same short carousel. Rather than force a fifth item to hit a round number, the carousel now honestly runs four confirmed surprises, matching the same discipline used to land on five instead of seven in the previous revision.

## Renovation photo — cut

REMOVED, rev 6

Removed per Jake's note ("I really fucking hate this photo"). The plain interior repaint shot was not earning its own slide once the closing card below carries a real exterior photo of the house instead of a flat background, so this beat is dropped rather than defended.



## 7. Closing title card

real photo background

OPTION A SELECTED

UPDATED, rev 7

Per Jake's note, the closing card now uses a real photo of the house as its background instead of a flat dark panel, so it reads as this property's card, not a generic template. All three use the same December 2025 front-exterior shot from the hook slide for a consistent, recognizable background, and vary only the proof-line above the standing tagline, "Live with us. Work with us." Annotate whichever card below to pick it, or ask for a different background photo if this one does not read as the strongest option.



**Option A selected.** Options B and C are left in place below for reference, not removed, in case the choice changes before this ships.

### PRODUCTION NOTE

Background is the same real front-exterior photo used on the hook slide, with a dark bottom-weighted scrim for text legibility, same gold mark treatment as the sibling reel's closing card. No dollar figures, no claim of completion, no specific date.

- ☑ **Closer, picked.** Option A selected ("Renovation in progress. Live with us. Work with us."), on a real front-exterior photo background. Options B and C remain on slide 7 for reference only.
- ☑ **Real count and list of surprises.** Four items are now confirmed for this post: the cracked window frame, the bent fence, the octagonal gable window, and the basement's prior use. All nineteen Drive photos for this property have been downloaded and individually viewed, so this is the full real list this spec can responsibly produce, not a guess at a longer one. A fifth item (a closer basement-window photo) was cut per Jake's note for reading as redundant with item 1.
- ☑ **Garage fence debris slide, cut.** The previous open, unconfirmed slide 5 is removed. Two new confirmable items were found elsewhere in the folder to reach five honestly, so the unconfirmed debris photo is no longer needed to hit the count Jake asked for.
- ☑ **De-identify check.** All seven selected photos were individually viewed. No person is visible in any of them, so no blur or crop is needed for this post. Widening the review to all nineteen Drive photos did turn up one image with a person visible, mid-frame, shoveling snow near a backyard shed; that photo is not used here, both because of the visible person and because it is already in use in the sibling portfolio montage reel. This is a completed check, not an open question.
- ☑ **House number check.** Two of the newly reviewed photos plainly show the property's house number on a porch placard. Neither is used anywhere in this spec, consistent with the standing street-name-only rule.
- ☑ **Real photos only.** All seven images used in this spec, including the two new ones added this revision, were downloaded from the confirmed Drive file ID list, opened and visually inspected, and verified with the `file` command as genuine iPhone camera JPEGs with intact EXIF data, not screenshots, not generated, not corrupted.
- ☑ **No overlap with the reel.** All nineteen Drive file IDs for this property have now been checked against the sibling portfolio montage reel's assets. Two matches turned up among the newly reviewed photos (the new HVAC unit and mulch bed exterior, and the backyard shed shot with a person visible) and were excluded from this spec on that basis. The seven photos used here are all different stills from that reel.
- ☐ **Brand rules.** Checked against every visible caption above: no dollar figures, full state name (Indiana), street name only with no house number, no contractions, no em dashes, no adjectives beyond a literal material or color name.

East Victoria Street Surprises carousel spec · shavit-pipeline · annotate anything above, notes save to the pipeline inbox when served through `serve.py`.