

TEST REPORT

2603 - 12th Street, SE Salem, OR 97302 Voice: (503) 363-0473 FAX: (503) 363-8900

Aqua Pro Pump Service 36967 Plagmann Dr NE Albany, OR 97322

SAMPLE INFORMATION

Location: 308 NE South Nebergal Loop well os tap

Date Sampled: 4/21/2021 Sample Type: Water Time Sampled: 1345 Collected by: KB

CASE NARRATIVE

The analyses were performed according to the guidelines in the WATERLAB Corp Quality Assurance Program. This report contains analytical results for the sample(s) as received by the laboratory.

WATERLAB Corp certifies that this report is in compliance with the requirements of NELAC. No unusual difficulties were experienced during analysis of this batch except as noted below or qualified with data flags on the reports.

TESTING INFORMATION

Lab #: 20210421-040

Date Received: 4/21/2021 Time Received: 1537 Received by: SW Time Started: Date Started: 4/21/2021 1611 Tech: SW Date Read: 4/22/2021 Time Read: 1650 Tech: SW Date Reported: 4/23/2021 Reported By: MH

*Chlorine Residual: N/A Amount of Sample Used: 100 mls

Method Code: SM 20th ED 9223 P/A Colisure ®

TOTAL COLIFORM BACTERIA RESULTS

Analysis shows Total Coliform Bacteria to be: ABSENT

Absent= Acceptable Present= Unacceptable

E.COLI COLIFORM BACTERIA RESULTS

Analysis shows E. coli Bacteria to be:

ABSENT

E. coli is a sub-section of Total Coliform and its presence in water indicates that raw sewage is present in the water.

Explanation: When coliform bacteria are present in water, it is considered contaminated and therefore unsafe. Coliform organisms are found normally in discharges from the intestinal tract of man, animals or birds. Their presence in the water, therefore, must be considered as evidence of pollution. The laboratory examination determines the presence or absence of contamination at the time of sampling only. No definite conclusions should be drawn from a single bacterial examination.

* Chlorine Footnote: Chlorine in water will kill coliform bacteria. Presence of chlorine in a water sample should invalidate the test unless the water is from a system that is continuously chlorinated every day the water is in use.

Test results relate only to the parameters tested and to the samples as received by the laboratory. Test results meet all requirements of NELAC unless otherwise noted. This report shall not be reproduced except in full without written approval of Waterlab Corporation.

Approved by:

Page 1 of 1