

Historical Aerials

Source: NSW Spatial Services - Historical Imagery Viewer / Historical Aerial Photography collection.

Corrected indicative location: early aerial frames mark the position just above the oval feature identified in the historical aerials; the last three colour frames have been aligned closer to the prior marker position following review.


Historical aerial imagery sourced from NSW Spatial Services shows a repeated oval/circular ground feature in the paddock area near 6 Bulwer Road / Lot 4 DP746930. The feature is consistent with a rural/equine exercise or training ring, riding track, holding yard, or other maintained agricultural ground feature. While the exact use should be described as indicative unless confirmed by a council, title, or local-history record, its repeated appearance across multiple years is strong visual evidence that the land had been cleared, shaped, accessed, maintained and disturbed, rather than remaining untouched or uncleared native land.

Why this matters

- The oval feature appears in more than one aerial year, suggesting it is a real ground feature rather than a photographic blemish.
- The surrounding area shows open paddocks, tracks, rural access, dams/ponds, fence lines and later development disturbance.
- The feature supports a history of rural land management and ground disturbance, whether it was used for horses, livestock, training, exercising, or another agricultural purpose.
- This evidence directly responds to the proposition that the land was historically not cleared: the NSW Spatial Services aerial photographs show a managed and modified rural landscape.

Corrected view: 23/09/1991 - 6 Bulwer Road / Lot 4


NSW frame 4042_02_037 | Film 4042 | Run R2 | Frame 37 | Scale 1:25000



Indicative marker corrected from user review, later colour frames aligned to previous marker position. Not a surveyed overlay.

Corrected view: 19/08/1963 - 6 Bulwer Road / Lot 4

NSW frame 1189_1M_091 | Film 1189 | Run R1M | Frame 5091 | Scale 1:38000



Indicative marker corrected from user review, later colour frames aligned to previous marker position. Not a surveyed overlay.

Images above: corrected indicative marker. Source: NSW Spatial Services Historical Imagery Viewer.

Historical Aerials

Source: NSW Spatial Services - Historical Imagery Viewer / Historical Aerial Photography collection.

The following corrected images are included as a visual exhibit. They should be read as indicative historical aerial interpretation, not as a surveyed cadastral overlay.

Corrected view: 29/12/1974 - 6 Bulwer Road / Lot 4

NSW frame 2288_1M_130 | Film 2288 | Run R1M | Frame 130 | Scale 1:40000



Indicative marker corrected from user review; later colour frames aligned to previous marker position. Not a surveyed overlay.

Corrected view: 8/01/1979 - 6 Bulwer Road / Lot 4

NSW frame 2729_01_111 | Film 2729 | Run R1 | Frame 111 | Scale 1:45300



Indicative marker corrected from user review; later colour frames aligned to previous marker position. Not a surveyed overlay.

Corrected view: 25/02/1989 - 6 Bulwer Road / Lot 4


NSW frame 3645_01_233 | Film 3645 | Run R1 | Frame 233 | Scale 1:40000



Indicative marker corrected from user review; later colour frames aligned to previous marker position. Not a surveyed overlay.

Corrected view: 24/09/1991 - 6 Bulwer Road / Lot 4

NSW frame 4041_01_141 | Film 4041 | Run R1 | Frame 141 | Scale 1:25000



Indicative marker corrected from user review; later colour frames aligned to previous marker position. Not a surveyed overlay.

Corrected view: 21/01/1997 - 6 Bulwer Road / Lot 4

NSW frame 4345_01_147 | Film 4345 | Run R1 | Frame 147 | Scale 1:50000



Indicative marker corrected from user review; later colour frames aligned to previous marker position. Not a surveyed overlay.

Note: the marker was corrected following review of the oval feature and later colour frame alignment. The marker is deliberately described as indicative. Source imagery: NSW Spatial Services.