

Inspection performed by Carlos Garcia on 2023-10-07.

All measured values are timestamped for audit purposes. This report presents the dimensional measurements and inspection results. Ensure measurement methods align with calibration standards. The following data captures key dimensions and any deviations identified. Use this examination summary to confirm component conformity.

Environmental Conditions: Temperature: 23.1 °C, Humidity: 58 %

Item Code	Component	Dim.	Nominal	Actual	Diff	Status (V/X)
VF-220D	O-Ring NBR 60mm	Thickness	92.19	92.01	-0.18	V
CE-905L	O-Ring NBR 60mm	Inner Diameter	74.40	74.42	+0.02	V
VR-940T	Hinge Set	Inner Diameter	48.70	48.51	-0.19	V
QP-660F	Rubber Gasket 80mm	Width	12.21	12.05	-0.16	V
SL-430M	Wooden Pallet	Height	45.28	45.24	-0.04	V
TY-350G	Hinge Set	Inner Diameter	87.59	87.50	-0.09	V
KV-390K	Bearing 6202 ZZ	Height	50.12	50.03	-0.09	V
MX-450L	Graphite Pad	Hole Ø	58.74	58.82	+0.08	V
TX-820V	Steel Sheet A36	Hole Ø	94.83	94.95	+0.12	V
RE-850C	Graphite Pad	Depth	72.76	72.78	+0.02	V