

Inspection Results Summary

Inspection performed by Anna Nowak on 2024-08-10.

This report presents the dimensional measurements and inspection results. Check that all dimensions comply with ISO and company standards. This summary of measurements supports metrology traceability. Review recorded tolerances against engineering specifications.

Environmental Conditions: Temperature: 24.1 °C, Humidity: 58 %

Product Ref	Part Name	Dim.	Nominal	Actual	Diff	Status (V/X)
GH-770J	Power Switch	Hole Ø	56.26	56.14	-0.12	OK
VF-220D	Hinge Set	Hole Ø	85.13	85.08	-0.05	OK
PW-515Y	Wooden Pallet	Thickness	50.81	50.92	+0.11	OK
SL-430M	Bearing 6202 ZZ	Thickness	77.11	76.99	-0.12	OK
SB-140D	Graphite Pad	Length	90.01	90.08	+0.07	OK
QP-660F	Wooden Pallet	Depth	30.38	30.41	+0.03	OK
XD-710R	Bearing 6202 ZZ	Inner Diameter	81.61	81.64	+0.03	OK
AL-115Q	Steel Sheet A36	Inner Diameter	14.11	13.92	-0.19	OK
AZ-300T	Bearing 6202 ZZ	Thickness	90.72	90.70	-0.02	OK
AZ-300T	Wooden Pallet	Inner Diameter	9.33	9.19	-0.14	OK
FT-730X	Battery Pack	Depth	56.50	56.51	+0.01	OK
GL-980S	Graphite Pad	Width	5.28	5.32	+0.04	OK