

Maintenance Checklist Report #5953631

Date: 2023-11-18

Unit Code	Equipment	Service Type	Operator	Duration	Site	Notes
MC-222	Assembly Robot	Corrective	Jan Kowalski	2.1	Plant 3A	Worn gasket replaced.
MC-245	Packaging Line	Corrective	Jan Kowalski	2.1	Plant 3A	Calibration check OK.
MC-249	Conveyor Belt	Preventive	Jan Kowalski	2.4	Plant 1C	Switch contacts cleaned.
MC-243	Laser Cutter	Inspection	Jan Kowalski	3.8	Plant 1C	Tightened loose bolts.
MC-215	Paint Booth	Preventive	Laura Rossi	1.6	Plant 1C	Replaced coolant.
MC-252	Assembly Robot	Corrective	Jan Kowalski	3.2	Plant 2B	
MC-261	Plasma Cutter	Preventive	Peter Schmidt	2.2	Plant 2B	Switch contacts cleaned.

Overall equipment condition is satisfactory post-maintenance. This log summary supports the asset-management dashboard. All maintenance tasks have been completed as per schedule. Record any spare parts usage for inventory adjustment.

Lubrication Checked	Yes
Calibration Verified	N/A
Emergency Stop Tested	No

Approved by: _____ Serviced by: _____