

Maintenance Checklist Report #7371372

Date: 2024-10-21

Machine ID	Machine	Service Type	Technician	Downtime	Area	Comments
MC-296	Hydraulic Press	Corrective	Laura Rossi	3.8	Plant 3A	Changed oil and filters.
MC-231	Lathe	Preventive	Carlos Garcia	1.8	Plant 3A	Worn gasket replaced.
MC-255	Plasma Cutter	Corrective	Anna Nowak	3.7	Plant 1C	Calibration check OK.
MC-285	Lathe	Inspection	Jan Kowalski	3.7	Plant 3A	Sensor recalibrated.

Flag any recurring issues for root-cause investigation. Record any spare parts usage for inventory adjustment. Overall equipment condition is satisfactory post-maintenance. All maintenance tasks have been completed as per schedule.

Lubrication Checked	Yes
Calibration Verified	Yes
Emergency Stop Tested	No

Approved by: _____ Serviced by: _____