

Equipment Record Report #7685673

Date: 2024-06-07

Machine ID	Equipment	Service Type	Operator	Downtime	Area	Notes
MC-232	Packaging Line	Corrective	Laura Rossi	2.3	Plant 2B	Sensor recalibrated.
MC-225	Plasma Cutter	Preventive	Peter Schmidt	3.0	Plant 1C	Li-Ion battery pack serviced.
MC-222	Packaging Line	Inspection	Carlos Garcia	3.0	Plant 2B	
MC-213	Laser Cutter	Preventive	Peter Schmidt	3.4	Plant 3A	Calibration check OK.
MC-287	Assembly Robot	Corrective	Carlos Garcia	2.6	Plant 3A	Tightened loose bolts.
MC-258	Packaging Line	Inspection	Laura Rossi	3.6	Plant 3A	Tightened loose bolts.
MC-256	Assembly Robot	Inspection	Peter Schmidt	1.6	Plant 1C	Replaced coolant.
MC-291	Plasma Cutter	Corrective	Peter Schmidt	2.7	Plant 1C	Li-Ion battery pack serviced.
MC-207	Laser Cutter	Inspection	Laura Rossi	2.8	Plant 1C	Li-Ion battery pack serviced.

Maintenance notes are archived for compliance audits. Overall equipment condition is satisfactory post-maintenance. Refer to remarks for any follow-up actions or parts replacements. Record any spare parts usage for inventory adjustment.

Lubrication Checked	No
Calibration Verified	Yes
Emergency Stop Tested	Yes

Authorized by: _____ Operator: _____