

Equipment Record Report

Performed On: 2024-07-26

Signed off:	Anna Nowak
Performed by:	Laura Rossi

The following entries detail preventive and corrective maintenance tasks. All technician comments are recorded for maintenance trend analysis. The equipment log below includes fault codes and corrective notes. Use this summary to forecast parts replacement and resource needs. This maintenance extract is prepared for compliance audit trails. Below is the summary of service actions and downtimes for each machine.

Section A:

Unit Code	MC-239	MC-298	MC-246	MC-243	MC-220	MC-214
Equipment	Hydraulic Press	Plasma Cutter	Hydraulic Press	CNC Milling Machine	Plasma Cutter	Hydraulic Press
Service Type	Preventive	Preventive	Preventive	Preventive	Inspection	Inspection
Technician	Laura Rossi	Laura Rossi	Anna Nowak	Anna Nowak	Laura Rossi	Jan Kowalski
Duration	2.7	2.1	2.3	2.0	3.5	3.0
Notes	Alignment of hinges adjusted.	Refilled oil (HLP 46).	Replaced coolant.		Li-Ion battery pack serviced.	Changed oil and filters.

Section B:

Unit Code	MC-246	MC-239	MC-243	MC-220	MC-214	MC-298
Equipment	Hydraulic Press	Hydraulic Press	CNC Milling Machine	Plasma Cutter	Hydraulic Press	Plasma Cutter
Service Type	Preventive	Corrective	Corrective	Corrective	Preventive	Preventive
Technician	Laura Rossi	Jan Kowalski	Anna Nowak	Jan Kowalski	Carlos Garcia	Carlos Garcia
Duration	3.1	1.8	1.8	2.3	1.6	3.3
Notes		Calibration check OK.	Changed oil and filters.		Sensor recalibrated.	Sensor recalibrated.

Uptime (%)	Error Count	Comments
98.83%	5	Bolt tightened