

9:41

4G 100%



Field Officer App

Water Distribution Management



Username / Staff ID

FO12345



Password

.....



Remember me

[Forgot Password?](#)



Login

OR



Login with Fingerprint



Secure Access


Your data is protected



Offline Ready

Works without internet

© 2025 Water Department
All rights reserved.



9:41

4G 100%



Capture Meter Reading

Field Officer App



Customer Details

John Mwangi

123 River Road, Riverside Estate
Nairobi, Kenya



Meter Number
MT12345678



Account Number
ACC9876543



Route / Zone
Route 12A / Zone 5



Previous Reading
1,245 m³



Reading Date
18 May 2025



Current Reading (m³)

m³

⚠ Current reading cannot be lower than previous.



Calculated Consumption

Will be calculated automatically

– m³



Capture Photo
Add meter photo



Capture GPS
Record location



Save Draft



Submit Reading



Secure Access
Your data is protected



Offline Ready
Works without internet

9:41

4G100%

Meter Photo & GPS Capture

Capture meter photo and location

Customer

John Doe

CUST123456

Meter ID

MTR987654

15 mm • Active

Meter Photo

ZENNER

0012345 m³

Qn 1.5
Pn 15
H-B
30°C

ZR 12345678

✓ Photo captured

Retake

Use Photo

Location (GPS)

12.9716° N, 77.5946° E

Accuracy: 5.0 m

May 22, 2025 • 09:41 AM

✓ Location captured

Photo captured

✓

GPS captured

✓

Attach to Reading

9:41

4G 100%



Work Order Details



Work Order ID

WO12345678



Task Type

Leak Repair



Customer / Zone

Central Zone



Location

123 Water Street,
Riverside, CA 92501



Scheduled Date

May 16, 2025 • 09:00 AM



Priority

High



Description

Repair reported leak on 8-inch main line near hydrant.
Restore service and ensure area safety.

Status



Assigned



Accepted



In Progress



Completed



Escalated



Accept the task to begin. Update status as work progresses.



Notes

Add notes about the work...



Start Time

Not started



Completion Time

Not completed



Evidence Add photos or attachments



Add Photo



Accept Task



Start Work



Complete



Escalate

9:41

4G100%

<

Site Inspection Report

Field Officer App

Application Reference

APP-2025-06789

Applicant Name

John Mwangi

Site Location

Kiambu County, Ruiru Ward

Scheduled Inspection Date

22 May 2025, 10:00 AM

Inspection Checklist

1. Accessibility to Site

Yes

No

N/A

2. Meter Point Availability

Yes

No

N/A

3. Pipeline Distance (<= 100m)

Yes

No

N/A

4. Pressure Suitability

Yes

No

N/A

5. Required Materials Available

Yes

No

N/A

Findings

Enter findings...

Recommendations

Enter recommendations...

Estimated Material Cost (KSh)

Enter amount

Estimated Labour Cost (KSh)

Enter amount

Site Photos

Tap to upload photos
PNG, JPG up to 5MB

GPS Capture

Location Captured

Lat: -1.234567, Long: 36.987654

Inspection Recommendation

Recommended

Not Recommended

Save Draft

Submit Inspection

9:41

4G100%

←

Disconnection Evidence



Field Officer App

Water Distribution Management

Account Information

 Customer Name
John Doe

 Notice Reference
N-2025-04567

 Account Number
AC12345678

 Reason for Disconnection
Non-Payment

 Outstanding Balance
\$125.75

 Location
123 River Road,
Springfield, ST 01103

 Disconnection Date & Time

May 28, 2025 10:45 AM

▼

 Evidence Photo



 GPS Coordinates

41.7812° N, 72.6841° W



 Customer Acknowledgement

Customer refused to sign

▼

 Remarks

Meter disconnected due to
outstanding balance.

☒

I confirm the disconnection has been completed.

 Capture Evidence

 Save

 Submit Disconnection

9:41

4G100%

←

Reconnection Evidence

Capture and submit reconnection details

✓

Reconnection captured successfully

Please review details and submit.

Customer Account

ACC-789456

✂

Disconnection Reference

DISC-2025-0715-1023

📄

Payment Confirmation

PAY-2025-0720-8831

📅

Reconnection Date & Time

20 Jul 2025, 10:45 AM

📍

Location

24, Waterworks Road,
Lagos, Nigeria

⚙

Service Status

✓ Reconnected

Captured Evidence Photo



📷 Capture Evidence

Retake or capture a new photo if needed.

📍 GPS Coordinates

6.5244° N, 3.3792° E

📍

💬 Remarks

Service reconnected successfully.
Water flow confirmed at the premises.

📁 Save

🚀 Submit Reconnection

9:41

4G100%

Field Officer App
Water Distribution Management

Materials Used & Customer Signature

Record materials used and capture customer signature to complete the job.

Work Order
WO-2025-0786

Date
May 15, 2025 • 10:30 AM

Customer Details

Name
John Mwangi

Customer ID
CUST-0089456

Materials Used

Item	Quantity	Unit	
Pipe (HDPE 25mm)	10	m	⋮
Valve (Ball Valve 25mm)	1	pcs	⋮
Meter Seal	1	pcs	⋮
Fittings (Reducer 25x20mm)	2	pcs	⋮

Customer Signature

Customer Name
John Mwangi

Customer ID
CUST-0089456

Save

Submit Job

Secure Access
Your data is protected

Offline Ready
Works without internet

