



Original
pothole.jpg



Grad-CAM heatmap




Pred: pothole (47.7%)




Original
crack.jpg



Grad-CAM heatmap




Pred: pothole (45.8%)



Original
manhole.jpg



Grad-CAM heatmap



Pred: manhole (66.8%)

