

NAME: JASMINE U
REG NO: 23MIS0078
COURSE TITLE: UI/UX LAB
COURSE CODE: ISWE407P

ASSIGNMENT - 1

BAD DESIGN:

1. Face Attendance Device Behind the Door



Description: The face attendance system is installed behind the classroom door, making it difficult to notice and access when the door is open. Its location interrupts the natural flow of students entering the classroom and creates congestion near the entrance. Since the device is placed right at the doorway, a student can record attendance and easily leave the class without actually attending the lecture. This placement affects both usability and the effectiveness of the attendance system.

2. Door Without Push/Pull Sign



Description: The classroom door does not have any "Push" or "Pull" indication, making its operation unclear for users. Students and visitors often hesitate before opening the door or try the wrong action first. This increases interaction time and creates unnecessary confusion. A simple label or a better-designed handle would improve the overall user experience.

3. Overcrowded Bag Rack



Description: The bag rack is overcrowded, making it difficult for students to locate and retrieve their bags quickly. Since there are no labels or organized sections, students spend extra time searching through multiple compartments. This creates congestion before and after class when many students access the rack simultaneously. A better storage layout with numbered compartments would improve the user experience.

4. Overloaded Notice Board



Description: The notice board contains too many notices displayed without proper organization or visual hierarchy. Important announcements are mixed with less relevant information, making them difficult to identify quickly. Students may overlook deadlines, academic updates, or event information because of the cluttered layout. Organizing notices into categories and removing outdated content would improve readability and usability.

5. Classroom with Limited Walking Space



Description: The classroom has too many chairs arranged with very little space between rows, restricting student movement. Entering, exiting, or reaching a seat becomes inconvenient, especially when the class is full. The cramped layout also makes emergency evacuation more difficult. A better seating arrangement would improve accessibility and classroom usability.

6. Window Without Safety Net



Description: The classroom window does not have a protective mesh or safety grill, allowing small items to accidentally fall outside. Students may lose pens, notebooks, or other belongings while sitting near the window. Retrieving these items can be difficult and inconvenient. Adding a safety mesh would prevent such issues without affecting ventilation.

7. Poor Placement of Drainage Near Classroom Entrance



Description: The open drainage channel is located directly in front of the classroom, reducing the usable space outside the room. Students avoid sitting or gathering near this area because of the drainage, limiting the corridor's intended use as a waiting or interaction space. The exposed drain also creates an unpleasant user experience and may pose a safety risk if someone accidentally steps into it. Relocating the drainage or covering it with a proper grate would improve both accessibility and the overall user experience.