Pipeline Inspection Report

Per-pipeline inspection history and sensor findings from the supplied API snapshot.

Report ID: AS-INS-2026-11-02 **Report date:** 02 November 2026 **Area:** Nagin Nagar

Inspection snapshot

Pipelines	Healthy	Moderate	Critical	Network length
8	3	3	2	8,700 m

Pipeline sensor readings

Pipeline	Pipeline name	Status	Score	Pressure	Flow	Temp °C	Motion	Vibration
PL-1001-R	Nagin Nagar - Main Pipeline	MODERATE	43.74	2.10	27.89	37.10	0.47	4.47
PL-1002-R	Nagin Nagar - North Section	HEALTHY	82.73	3.71	52.06	25.28	0.05	1.20
PL-1003-R	Nagin Nagar - South Section	CRITICAL	16.24	1.13	17.47	44.64	1.24	7.38
PL-1004-R	Nagin Nagar - East Section	MODERATE	43.81	1.86	28.23	35.80	0.57	4.11
PL-1005-R	Nagin Nagar - West Section	HEALTHY	86.93	4.80	50.73	25.76	0.16	1.01
PL-1006-R	Nagin Nagar - Extension A	CRITICAL	14.59	1.30	6.15	41.35	1.14	7.26
PL-1007-R	Nagin Nagar - Extension B	MODERATE	44.19	1.89	24.68	36.22	0.40	3.65
PL-1008-R	Nagin Nagar - Distribution Line	HEALTHY	85.22	3.78	45.17	20.52	0.07	0.18

Asset details

PL-1001-R — Nagin Nagar - Main Pipeline
Diameter: 150 mm | Material: Ductile Iron | Length: 1200 m | Operational status: Active
Recorded: 2026-11-02 00:40:02.025586

PL-1002-R — Nagin Nagar - North Section
Diameter: 150 mm | Material: Ductile Iron | Length: 850 m | Operational status: Active
Recorded: 2026-11-02 00:40:02.013463

PL-1003-R — Nagin Nagar - South Section
Diameter: 100 mm | Material: PVC | Length: 650 m | Operational status: Active
Recorded: 2026-11-02 00:40:02.002093

PL-1004-R — Nagin Nagar - East Section
Diameter: 200 mm | Material: Cast Iron | Length: 1500 m | Operational status: Active
Recorded: 2026-11-02 00:40:01.977968

PL-1005-R — Nagin Nagar - West Section
Diameter: 150 mm | Material: Ductile Iron | Length: 1100 m | Operational status: Under Maintenance
Recorded: 2026-11-02 00:40:01.965676

PL-1006-R — Nagin Nagar - Extension A
Diameter: 100 mm | Material: HDPE | Length: 950 m | Operational status: Active
Recorded: 2026-11-02 00:40:01.954008

PL-1007-R — Nagin Nagar - Extension B
Diameter: 200 mm | Material: Ductile Iron | Length: 1750 m | Operational status: Active
Recorded: 2026-11-02 00:40:01.597596

PL-1008-R — Nagin Nagar - Distribution Line
Diameter: 150 mm | Material: PVC | Length: 700 m | Operational status: Active
Recorded: 2026-11-02 00:40:01.572836

Scope note: This report represents the supplied sensor snapshot. It does not confirm physical leakage or structural defects. Zone was null in all supplied records.