

Motor Vehicle Repair History

Agency: **Department of Information and Communications Technology**

Province: **Tuguegarao City, Cagayan**

Type: **UTILITY VAN**

Brand/Model: **NISSAN URVAN NV350**

Engine No: **YD25004704B**

Plate Number: **SAA 1141**

Chassis No: **JN1TC2E26Z0016641**

Year Model: **2018**

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
3-Jun-26	Repair of airconditioning system	Full charge freon	lot	1	₱12,540.00
		Oil	bottle	1	
		Assorted O-rings	lot	1	
		Flashing 141B	can	3	
		Filter drier	piece	1	
		Evaporator	piece	1	
3-Jun-26	Repair of airconditioning system	Auxilliary fan	piece	1	₱5,500.00
19-Jul-24	Change oil	Gasket Drain plug	Pc	1	₱665.00
		Filter Oil	Pc	1	₱750.00
		Filter A/C Fresh Air	Pc	1	₱1,500.00
		Filter Air Cleaner	Pc	1	₱2,180.00
		Universal Cleaner	Pc	1	₱500.00
		Engine Oil	Pcs	9	₱600.00
24-Jul-24	Replacement of front break pads	Brake Pad Front	Pc	1	
	Replacement of left rear tail light	Tailight (LEFT)	Pc	1	₱4,500.00
16-Oct-24	Replacement of left rear tail light	Labor	lot	1	₱2,000.00
28-Oct-24	Body Repair	Body repair and repainting	lot	1	₱9,700.00
3-Dec-24	40k Preventive Maintenance	Filter Oil			₱720.00
		Engine Flush	PC	1	₱600.00
		Universal Cleaner	BTL	2	₱385.00
		Winshield Washer (40ML)	BTL	1	₱200.00
		Diesel Smoke Stop	BTL	1	₱750.00
		Gasket Drain plug	BTL	2	₱630.00
		Aircon Cleaner and Disinfect	PC	1	₱650.00
		Filter A/C Fresh Air	ASY	1	₱1,500.00

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
3-Dec-24	40k Preventive Maintenance	Anti Freeze	PC	1	₱1,800.00
		Engine oil	LTR	8	₱600.00
		Miscellaneous	UN	1	₱448.00
17-Feb-25	Battery Replacement	Battery DIN 80	Unit	1	₱9,500.00

I hereby certify that the above listed were the repairs actually undertaken as of _____ that is based on the submitted "Vehicle Monthly Repair Log" and on available records in this office.

Ronald S. Bariuan
OIC, Motor Pool Unit