

G7 Geometry pipeline and the gate table, including what fails

Geometry and physics gates, measured this session

gate	measured value	verdict
------	----------------	---------

mesh containment of solid particles	1000 particles, 2000 samples	PASS
-------------------------------------	------------------------------	------

fill_ratio vs 0.95 to 1.10	0.9941 to 1.00262 (17 runs)	PASS
----------------------------	-----------------------------	------

water surface open_edges		PASS
--------------------------	--	------

water volume error	+1.68% raw, +1.65% smoothed	PASS
--------------------	-----------------------------	------

oob_particle_frames	0	PASS
---------------------	---	------

determinism_identical	True, all 17 runs	PASS
-----------------------	-------------------	------

realized rho vs the 1000/300 base kg/m3	658 kg/m3	FAIL
---	-----------	------

water particle passthru	7.3 pct; 15.9 pct; won't allow = 3.0 m/s	NOTED
-------------------------	--	-------

Hull geometry, one mesh: yaris_coarse_v11_watert

measured ground

clearance BAND

0.158 to 0.174m

(five sampling bands)

Yaris hull, side view

(width) = 1.746378m

g axis Y = 4.282610m

U=8.000m/s
Z