PROPERTY KNOWN AS

47 Lingtry Court belfast

INVENTORY / Schedule of condition

TENANTED PROPERTY 47 Langtry Court LANDLORD DETAILS Elizabeth McDermott Inspection Date: Check In Inspection Date: Check Out	
Inspection Date : Check In 8 th October 2021- Ronan	
Inspection Date : Check Out	
Declaration All items have been inspected on check in and check out and have found to be in the condition described	
CHECK IN	
TENANT HUST.	
AGENT Please sign and date on CHECK IN Please sign and date on CHECK OUT	
CHECK OUT	
TENANT	
AGENT Please sign and date on CHECK IN Please sign and date on CHECK OUT	
METER READINGS	
Please phone Airtricityimmediately, upon taking up occupancy of this property, and quote your name, address appropriate meter reading:	ess
Airtricity: 03456012705	
This number will get you through to their electricity department and after giving the electric account details can ask them to put you through to their gas department and you can set up your gas account.	s, you
Service Location Gas card meter below sink in Kitchen Gas Reading N/A card meter Gas reading Out	

Electricity Service Location - In cupboard outside below concrete steps Reading in N/A card meter Reading out

GENERAL - Regulations, Safety, Information

Gas Safety Certificate Check in - completed Check out

All furniture complies with fire regulations Check in - confirmed Check out

Smoke alarms / battery tested Check in – wired to mains in working order Check out

Front Entrance – professionally cleaned

Description – Entrance hall in good condition Check in Check out

Lights $-1 \times \text{light} - \text{bulb}$ in working order Check in Check out

Front door – in good order – some marks on front door from general wear and tear Check out

Hall, Stairs Landing - professionally cleaned

Description – Hall, stairs landing in good order – mark at top of stairs on wall Check in

Door & frame – all doors are in good order – some general signs of wear and tear on paintwork Check in

Ceiling –newly painted white 2021 October – in good condition Check in Check out

Walls – painted white newly painted October 2021 Check in Check out

Skirting boards – varnished – some light markings Check in Check out Flooring – carpet on stairs and landing, professionally cleaned – all in good order Check out

Lights – 2x lights with shades – all bulbs in working order Check in

Radiator – 1 x radiators– in good order-Check in Check out

Electrical sockets – all in good order – no damage Check in Check out

Furnishings – hall console table Check in Check out

Reception - professionally cleaned

Description – all in good order Check in Check out

Floor – carpet professionally cleaned Check in Check out

Walls –painted white in good order Check in Check out

Ceiling – painted white – in good order Check in Check out

Window – double glazed windows, in good order, Check in Check out

Doors – in good order Check in Check out

blinds – in good order Check in Check out Skirting – in good order Check in Check out

Lights— in good order — all bulbs in working order Check in Check out

Sockets – in good order Check in Check out

Radiator – in good order Check in Check out

Kitchen – professionally cleaned

Description – In excellent order, painted Oct 2021 and cleaned to a high standard Check in Check out

Floor – vinyl – in good order Check in Check out

Walls –painted white – Check in Check out

Ceiling -painted white – Check in Check out

Cupboards & Drawers - all in good order
Check in - doors how its we closing where gas meter it setup
Check out

Sinks / taps / drainer – in good order Check in Check out

Worktops – some burn marks to left of sink Check in Check out

Lights -spotlights in good order - all spotlights in working order Check in - spot Leynes (middle) not working

Check out

Sockets – in good order Check in Check out

Stove / Oven/ Extractor/Hob Check in Bulls on extractor not working
Check out

Fridge/freezer - in good, working order - professionally cleaned Check in Speezer has crack on the Professionally Cleaned Check out

Window- double glazed – in good condition Check in Check out

Boiler & heating & hot water timer – in good order Check in Check out

washing machine in good order

check in Check out

Bathroom painted October 2021

Description – in good order Check in Check out

Floor—vinyl floor covering in good order Check in Check out

Walls —tiles and painted — in good order Check in $\label{eq:check} Check \ out$

Celling – white painted – in good order Check in Check out

Windows – double glazed – in good condition Check in Check out

Door – in good condition Check in Check out Skirting – painted white – in good order Check in Check out

Lights — In good order, Check in Check out

Tallet – white WC & WHB – in good order Check in Check out

Bath – white bath – in good order Check in Check out

Sink /taps – in good order Check in Check out

Shower – new electric shower Oct 2021 Check in Check out

Bedroom 1

Description – back bedroom Check in Check out

Floor – carpet – in good order, Check in Check out

Walls – painted Oct 2021 Check in Check out

Ceiling-painted white-Check in Check out

Windows - double glazed – in good order Check in Check out

Door – in good order Check in Check out

Blinds in good order Check in Check out Skirting – in good order showing wear and tear Check in Check out

 $\label{eq:lights-lightwith} \begin{tabular}{ll} Lights-1 \ x \ light with shade-bulb in working order \\ Check in \\ Check out \end{tabular}$

Sockets – in good order Check in Check out

Radiator – in good order Check in Check out

Bedroom 2 - Double Bedroom - Front - professionally cleaned

Description - all in good order
Check in Small 6-torage space, not cleaned.
Check out

Floor – carpet – in good order Check in Check out

Walls-painted-Check in — Some Ligns on the estrance and governd wears tear usage. Check out

Ceiling – painted white – in good order Check in Check out

Windows – in good order Check in Check out

Door – in good order Check in Check out

blinds –in good order 1 truck broken Check in Check out

Skirting – varnished – in good order Check in Check out

 $\label{light} \mbox{Lights} - 1 \times \mbox{light with shade} - \mbox{bulb in working order} \\ \mbox{Check in } \\ \mbox{Check out}$

Sockets – in good order Check in Check out

Radiator - in good order Check in Check out

Furnishings –double bed with good mattress chest of drawers fabric clothes hanger all in good order

Bedroom 3- Top master bedroom professionally cleaned, new carpet Oct 2021 newly painted Oct 2021

Description - all in good order Check in Check out

Floor carpet – in good order new October 2021 Check out

Walls – painted white Oct 2021 – in good order Check in Check out

Ceiling – painted white – in good order Check in Check out

Velux Windows – in good order - one tiest willing and large how torn tent Check out

Door - in good order Check in Check out

Skirting – varnished – in good order Check in Check out

Lights -light with shade - bulb in working order Check in Check out

Sockets - in good order

Check in Check out

Radiator - in good order

Check in Check out Furnishings – large wooden wardrobe with drawers – in good order, chest of drawers and 2 bedside lockers Check out

Furnishings – 6 drawer chest of drawers– in good order Check in Check out

Thermostat / timer Check in Check out

Smoke alarm on each floor Check in Check out

Keys Supplied ... Front door x 2 keys 2 electric cards 1 gas cards

General Notes

I the undersigned have checked thoroughly the statement of condition and have found it to be correct. It is agreed that this shall form the basis of any future assessment of dilapidations on my subsequent vacation of the property.

I agree the property has been professionally cleaned throughout to a high standard, including the kitchen appliances and bathroom. I agree I will leave the property in the same condition, when vacating, with the consideration of fair wear and tear.

Signature of Leaseholder (s)