


APMKINGSTRACKTECHNOLOGIES

OnlineVehicleTrackingDeviceCertificate AIS-140



To, TheRegionalTransportOfficer **METTUR**

CertificateNo.:TN15624CCTV IssuingDate:5/02/2025





VehicleOwnerDetails:		VahanDetails:	
Name:THECHAIRMAN		UniqueVLTDCode: APM1K2	
Address:STAREDUCATIONALTRUSTPINNO6/1-49NIRMALASCHOOLST KOLATHUR PO METTUR TK SALEM		VLTDSerialNo:APM1K2I102100007927	
Phone: 9894275686		FitmentCentrecode:122	
Email-ID:starhitechschool2010@gmail.com		Fitment Centre Name: APM KINGSTRACKTECHNOLOGIES	
Aadhar:801581159943	PAN:	DeviceManufactureYear:2019	

VLTDDetails:

VLTDSerialNo: APM1K2I102100007927	ICCIDNumber:8991102105467078073F
VLTDMODELNO/SOSMODELNO:1819001A/1819001B	DeviceActivation/CertificationDate:5/02/2025
TACNo:CL8506COPNO:CC0GQ8709/VALIDITY:04-02-2026	CertificateValidUpto:4/02/2026
VLTDTestReport:IRNSSCTOGO0273	SIMPROVIDER1(Vodafone):915754200064135
IMEINumber:865006044605898	SIMPROVIDER2(Bsnl):915752184724358

CertifiedBy:InternationalCentreForAutomativeTechnology(ICAT)

InstalledBy:	CertificateIssuedBy:
BLOOM TECHNOLOGIES	APMKINGSTRACKTECHNOLOGIES
	MBCOMPLEX,#25/142,LOGANATHAN NAGAR
	2NDST, JAWAHARLAL NEHRU
	SALAI, 100FTROAD, CHOOLAIMEDU, CHENNAI-94.

_			_		
Ca	mα	ra	מנו	toı	ıe.
va	IIIC	ıa	ᅜ	ιaı	ıə.

CameralMEI:

APMKTi3251021545

CameraSerial:

fa45837cb039810e





Camera Image



Capture dImage



This is to certify that following vehicle has been installed and activated with ICAT approved IRNSSVehicle Location Tracking Device as per AIS-140 Standard, The device warranty is void if device istampered or the seal is Broken by unauthorized technicians or individual

RTA/RTO/STASignature

This is to acknowledge and confirm that we have got our vehicle installed with above vehicle locationtracking unit. We have checked the performance of the vehicle after installation and we confirm VLD isfunctioning as per AIS-140 norms. We aresatisfiedwith the performance of the devicein al respects, we under take not to raise any dispute or any legal claims against M/SAPM kingstrack Technologies, Institution of the contraction of ttheeventthattheabovementionedfunctionis foundbroken/torn/tampered/afterexpiry&warrantydate