claim number 7007986837-1

New damage to areas outside of Farmer's 2020 own assessment

When we file the hail damage claim on 2020, the following hail damages were identified and approved by Farmers, as showing in FinalDocument.pdf for 2020 hail damage claim:

- 2 window sashes
- Roof
- Gutter
- Garage Door
- Front Door

As shown in the above document, there were only damages to 2 sashes. No damages were found to other windows. This means all the dents are newer, occurred after 2020.

Due to pandemic, we had to request for extension to get the work done:

From: **Ryan Gagner** ryan@inclineexteriors.com
Subject: claim 3013539499-1-1
Date: October 7, 2021 at 11:36 AM
To: myclaim@farmersinsurance.com, Bill Lu bill_y_lu@yahoo.com

RG

Hello!-
Please release any remaining depreciation remaining on the roof/gutters all work on the roof and gutters is complete.

We are working with metro garage door for the garage doors and with kelly enterprises on the windows/doors and we'll likely need an extension for those items.


Metro say's roughly 12 weeks once they order a door & on the front door & window(s) could be roughly 8-12 weeks.

Thank you for any consideration regarding timing on this project! Please call or email me with any questions.

Ryan Gagner
612-267-3133

Incline Exteriors
143 Oak St
Excelsior, MN 55331

Even with this extension, our contractor couldn't get work done with the 2 sashes, and the door replaced. We asked for second extension, but it's not approved. We run out of time to replace those 2 sashes and the front door.



Subset of the photos of newer hail damages

Dents to the window (west facing second floor bedroom, above dining room)



Dent to windows of family room













Master Bedroom





Subset of photos from the PRIEVE ENGINEERING LLC's report also shows newer hail damages:



A-39



A-40



A-41



A-42



A-45



A-49



A-5 0



A-53



A-54




A-55



A-56



A-92




A-93.



A-99



A-103



A-107



A-115




A-117



A-119




A-128



A-141



A-153



A-156




A-158



A-163



A-166



A-179