Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 7:00 PM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Window Wrap North Damaged - No



2. Window Wrap North Damaged - No_2



3. Window Wrap North Damaged - No_3



4. Window Wrap North Damaged - No_4



5. Window Wrap North Damaged - No_5



6. Window Wrap North Damaged - No_6



7. Window Wrap North Damaged - No_7



8. Window Wrap North Damaged - No_8



9. Window Wrap North Damaged - No_9



10. Window Wrap North Damaged - No_10



11. Window Wrap North Damaged - No_11



12. Window Wrap North Damaged - No_12



13. Window Wrap South Damaged - No



14. Window Wrap South Damaged - No_2




15. Window Wrap South Damaged - No_3




16. Window Wrap South Damaged - No_4



17. Window Wrap South Damaged - No_5




18. Window Wrap South Damaged - No_6



19. Window Wrap South Damaged - No_7



20. Window Wrap South Damaged - No_8



21. Window Wrap South Damaged - No_9



22. Window Wrap South Damaged - No_10



23. Window Wrap South Damaged - No_11



24. Window Wrap South Damaged - No_12



25. Window Wrap South Damaged - No_13



26. Window Wrap West Damaged - No



27. Window Wrap West Damaged - No_2



28. Window Wrap West Damaged - No_3



29. Window Wrap West Damaged - No_4




30. Window Wrap West Damaged - No_5




31. Window Wrap West Damaged - No_6



32. Window Wrap West Damaged - No_7



33. Window Wrap West Damaged - No_8



34. Window Wrap West Damaged - No_9




35. Window Wrap West Damaged - No_10



36. Window Wrap West Damaged - No_11



37. Window Wrap West Damaged - No_12



38. Window Wrap West Damaged - No_13

