Field inspection photos

PDF Created on September 6, 2024 at 13:27:35 PM

Claim Number: 7007986837-1

Front elevations of home overview











Right elevations of home overview



Rear elevations of home overview

















Left elevation of home overview

CHIPS



Homeowner has some water damage on interior not related to hail no penetrations or openings to cause this water there is somewhere in tear on caulking on the exterior of the windows and there was heavy wind driven rain around these areas

Following photo show front of home overview homeowner pointed these items out

Falling photo show rear photos homeowners pointed these items out













Fall photos show interior windows homeowners showed these items to me as well



Entry Guard

DEPRESS ARM
TO DETACH
TRUTH