

There are hails/storm damage to the exterior of property and leaking windows.



Damage to a window



Eat-in area window



Porch, 1-panel window



Porch, 1-panel window



Family room 1-panel window




Family room 3-panel window



Family room top 1-panel window



Kitchen window



Second floor bedroom on top of office



Window above front door



Second floor bedroom window
on top of dining room



Second floor bedroom window
on top of living room



Cracks: south side window on stairs



Cracks: south side window on stairs



A 6-inch branch was broken during the storm. we cleaned up. Stud was here for your reference.

