

PRIEVE ENGINEERING LLC
FORENSIC STRUCTURAL CIVIL

FILE NUMBER: 241008

17756 GEORGE MORAN DRIVE
EDEN PRAIRIE, MN 55347


PHOTO APPENDIX A

SITE VISIT DATE: OCTOBER 9, 2024

This document is copyright of Prieve Engineering LLC. Duplication or reproduction is prohibited. This document relates only to the subject address and is to be used only by the contracted party.



A-1: INTERIOR UPPER WINDOW ABOVE MAIN ENTRY



A-2: STAIN PATTERNS VISIBLE BELOW LEFT CORNER OF WINDOW




A-3: UPPER LEFT CORNER OF ENTRY DOOR, STAINING VISIBLE ON WALL



A-4: REAR NORTHEAST FACING WINDOW AT FAMILY ROOM



A-5: VIEW OF WALL BELOW LEFT CORNER OF WINDOW



A-6: CENTER WINDOW GROUP, EAST WALL, VIEW OF LOWER LEFT CORNER



A-7: LOWER RIGHT CORNER AT SASH, STAINING PRESENT



A-8: LOWER LEFT CORNER OF MAIN CENTER WINDOW GROUP, FAMILY ROOM



A-9: LOWER RIGHT CORNER OF CENTER WINDOW GROUP AT EAST FAMILY ROOM WALL



A-10: UPPER SOUTHEAST WINDOW IN FAMILY ROOM




A-11: LOWER SOUTHEAST FACING WINDOW IN FAMILY ROOM



A-12: LOWER LEFT CORNER OF WINDOW




A-13: LOWER RIGHT CORNER, DETERIORATION PRESENT



A-14: SOUTH STAIRWAY WINDOW, MAIN LEVEL TO UPPER LEVEL LANDING



A-15: LOWER LEFT CORNER OF WINDOW



A-16: LOWER CORNER OF WINDOW



A-17: SOUTHWEST WINDOWS AT LOWER STAIRWAY LANDING



A-18: WALL CORNER BETWEEN WINDOWS AT STAIRWAY



A-19: UPPER LEVEL FRONT WINDOW AT SOUTHWEST BEDROOM



A-20: LOWER LEFT CORNER OF WINDOW AT WALL




A-21: LOWER WINDOW CORNER, DETERIORATION PRESENT



A-22: REAR NORTHEAST BEDROOM, EAST WINDOW



A-23: WALL BELOW LEFT SIDE OF WINDOW



A-24: LOWER LEFT CORNER OF WINDOW



A-25: EXTERIOR, VIEW OF SIDING BELOW UPPER BEDROOM WINDOW



A-26: PENETRATION IN SIDING PANEL BELOW UPPER EAST BEDROOM WINDOW



A-27: VIEW OF PENETRATION IN SIDING PANEL



A-28: SOUTHEAST FACING WINDOW AT REAR MAIN LEVEL PORCH



A-29: VIEW OF WALLPAPER BELOW RIGHT SIDE OF WINDOW



A-30: LOWER RIGHT CORNER OF WINDOW, SOUTHEAST FACING



A-31: NORTHEAST FACING WINDOW IN REAR MAIN LEVEL PORCH



A-32: VIEW OF WALL BELOW RIGHT SIDE OF WINDOW



A-33: LOWER RIGHT CORNER OF WINDOW



A-34: LOWER LEFT CORNER OF NORTH WINDOW IN KITCHEN



A-35: VIEW OF JOINT IN TRIM AT LOWER LEFT CORNER OF KITCHEN WINDOW



A-36: LOWER LEFT CORNER OF WINDOW AT SASH




A-37: SOUTHEAST FACING WINDOW SOUTH OF DECK DOOR



A-38: MAIN LEVEL, WEST WINDOW NORTH OF ENTRY



A-39: VIEW OF DENT IN SASH AT RIGHT CASEMENT



A-40: DENT IN SASH ALONG LEFT SIDE OF CASEMENT



A-41: LEFT CASEMENT, VIEW OF DENT IN SASH




A-42: DOWNSPOUT EXTENSION AT FRONT, VIEW OF DENT AT UPPER EDGE



A-43: UPPER WINDOW, WEST SIDE NORTH OF ENTRY



A-44: VIEW ALONG BOTTOM OF WINDOW




A-45: DENTS WITH SHARP MARKS PRESENT AT LEFT SASH



A-46: LOWER RIGHT CORNER OF SASH AT UPPER WINDOW



A-47: VIEW ALONG BOTTOM OF WINDOW, UPPER WEST BEDROOM



A-48: UPPER WINDOW ABOVE MAIN ENTRY



A-49: LOWER RIGHT CORNER OF CENTER FIXED SASH



A-50: VIEW ALONG BOTTOM OF WINDOW FRAME, OUTWARD PROTRUSION



A-51: LOWER RIGHT CORNER OF UPPER WINDOW



A-52: MAIN LEVEL WINDOW, WEST SIDE SOUTH OF ENTRY



A-53: CHIP IN TRIM ALONG LEFT SIDE OF BUMP-OUT



A-54: VIEW OF FLASHING ALONG BOTTOM OF BUMP-OUT



A-55: LEFT SIDE OF WINDOW GROUP AT MAIN LEVEL IN BUMP-OUT



A-56: VIEW ALONG BOTTOM OF WINDOW FRAME



A-57: ADJACENT AREA ALONG BOTTOM OF WINDOW



A-58: RIGHT SIDE OF WINDOW, MAIN LEVEL, SOUTHWEST QUADRANT



A-59: UPPER BEDROOM WINDOW, WEST SIDE SOUTH OF ENTRY



A-60: LOWER RIGHT CORNER OF WINDOW



A-61: VIEW OF RIGHT MULLION



A-62: LEFT MULLION, CAULK PRESENT



A-63: LOWER LEFT CORNER OF WINDOW



A-64: SASH WITH DENT PRESENT AND SCRAPE MARK IN DENT



A-65: VIEW ALONG BOTTOM OF WINDOW FRAME



A-66: UPPER WINDOWS AT WEST SIDE, NORTH QUADRANT



A-67: LOWER LEFT CORNER OF LEFT UPPER WINDOW



A-68: LOWER LEFT CORNER OF RIGHT/SOUTH WINDOW AT UPPER LEVEL



A-69: SOUTH SIDE OF HOME, AREA OF STAIRWAY



A-70: SOUTH WINDOW AT MAIN LEVEL WEST OF STAIRWAY



A-71: WEST WINDOW AT LOWER STAIRWAY



A-72: LOWER RIGHT CORNER OF WEST FACING WINDOW AT STAIRWAY



A-73: UPPER WEST WINDOW AT UPPER STAIRWAY LANDING



A-74: UPPER SOUTH FACING WINDOW WEST OF STAIRWAY



A-75: LOWER STAIRWAY WINDOW GROUP, SOUTH WALL



A-76: LOWER LEFT CORNER OF WINDOW



A-77: LOWER RIGHT CORNER OF WINDOW AT LOWER STAIRWAY LANDING



A-78: VIEW ALONG BOTTOM OF WINDOW



A-79: WINDOW GROUP AT UPPER STAIRWAY LANDING, SOUTH WALL



A-80: VIEW ALONG BOTTOM OF WEST SASH AT LOWER WINDOW



A-81: LOWER RIGHT CORNER OF UPPER STAIRWAY WINDOW GROUP



A-82: MULLION AT WINDOW, CUALK PRESENT




A-83: UPPER PORTION OF MULLION AT STAIRWAY WINDOW GROUP



A-84: LEFT MULLION AT STAIRWAY WINDOW GROUP



A-85: UPPER WEST WINDOW AT STAIRWAY



A-86: LEFT SIDE OF UPPER CENTER WINDOW



A-87: RIGHT MULLION AT UPPER WINDOWS, CAULK PRESENT



A-88: VIEW OF UPPER MULLION INTERSECTION AT STAIRWAY WINDOWS



A-89: WEST FACING WALL AT PROJECTION ON SOUTH SIDE EAST OF STAIRWAY



A-90: AREA OF CHIPPED FINISHES AT TRIM BOARD



A-91: DOWNSPOUT EXTENSION AT SOUTH SIDE OF HOME



A-92: VIEW OF DOWNSPOUT, DENT PRESENT



A-93: ADJACENT AREA SHOWING DENT IN DOWNSPOUT



A-94: OVERVIEW OF EAST SIDE OF HOME




A-95: LOWER WINDOW GROUP UNDER DECK AT SOUTH QUADRANT



A-96: LOWER DOOR AND WINDOWS BELOW DECK, ADJACENT AREA TO THE NORTH



A-97: ADJACENT LOWER WINDOW GROUP UNDER PORCH AT EAST SIDE



A-98: DOWNSPOUT AT EASET SIDE SHOWING DENT




A-99: DENT IN DOWNSPOUT WITH CREASE PRESENT



A-100: LOWER LEVEL WINDOW GROUP, EAST SIDE AT NORTH QUADRANT



A-101: EAST WINDOW GROUP IN FAMILY ROOM AT MAIN LEVEL



A-102: LOWER SOUTHEAST FACING WINDOW



A-103: VIEW OF DENTS IN FLASHING AT BASE OF WALL ALONG DECK



A-104: UPPER LEFT CORNER OF SOUTHEAST FACING LOWER WINDOW



A-105: LEFT SIDE AT SOUTHEAST FACING WINDOW



A-106: UPPER SOUTHEAST FACING WINDOW AT FAMILY ROOM



A-107: LOWER RIGHT CORNER OF WINDOW



A-108: MAIN EAST FACING WINDOW GROUP AT FAMILY ROOM



A-109: BOTTOM OF RIGHT CASEMENT



A-110: VIEW OF RIGHT MULLION



A-111: SCRAPE MARKS AT MULLION



A-112: LEFT SIDE OF WINDOW FRAME



A-113: VIEW OF DENT WITH SCRAPE MARKS AT UPPER PORTION OF WINDOW



A-114: VIEW ALONG SILL, DENT WITH SCRAPE MARK



A-115: LOWER LEFT CORNER, 2 DENTS PRESENT ALIGNED VERTICALLY



A-116: UPPER DENT, SCRAPE MARK PRESENT



A-117: VIEW OF LOWER DENT, VARIOUS SCRAPE MARKS ON SURFACES



A-118: UPPER EAST WINDOW GROUP AT FAMILY ROOM



A-119: VIEW OF DENT IN DRIP CAP WITH MARK PRESENT IN DENT



A-120: ADJACENT AREA ALONG TOP OF UPPER WINDOW



A-121: LOWER PORTION OF WINDOW, SCRAPE MARK PRESENT



A-122: VIEW ALONG BOTTOM OF WINDOW FRAME



A-123: VIEW ALONG BOTTOM OF WINDOW FRAME



A-124: LOWER RIGHT CORNER OF WINDOW



A-125: NORTHEAST FACING WINDOW AT FAMILY ROOM



A-126: LOWER RIGHT CORNER OF WINDOW



A-127: LOWER LEFT CORNER, LOWER NORTHEAST FAMILY ROOM WINDOW



A-128: VIEW OF FLASHING AT DECK ALONG BASE OF WALL



A-129: ADJACENT AREA SHOWING FLASHING ALONG DECK AT EAST WALL



A-130: SCRAPE MARK ALONG BOTTOM FRAME OF WINDOW



A-131: VIEW ALONG BOTTOM OF WINDOW, NORTHEAST FACING FAMILY ROOM



A-132: VIEW OF DRIP CAP ABOVE WINDOW, NO DENTS OBSERVED




A-133: UPPER NORTHEAST FACING WINDOW AT FAMILY ROOM



A-134: DENT IN BOTTOM OF WINDOW FRAME AT ACCESSORY GROOVE



A-135: VIEW OF FACE OF WINDOW FRAME AT UPPER NORTHEAST WINDOW UNIT




A-136: WINDOW AND SLIDING DOOR, EAST SIDE AT DECK



A-137: LOWER LEFT CORNER OF WINDOW, SOUTHEAST FACING



A-138: LOWER RIGHT CORNER OF WINDOW



A-139: RIGHT SIDE, SCRAPE MARK IN FRAME



A-140: VIEW OF SCRAPE MARKS IN FRAME AND SASH



A-141: DENT IN SCREEN AT DOOR WINDOW SCRAPE MARK PRESENT



A-142: UPPER WINDOWS, EAST WALL AT SOUTH QUADRANT



A-143: LOWER LEFT CORNER OF SOUTH WINDOW



A-144: LOWER RIGHT CORNER, CAULK AT WINDOW CORNERS



A-145: NORTH WINDOW AT UPPER FAMILY ROOM



A-146: SCRAPE MARK ALONG LEFT SIDE OF SASH AT NORTH WINDOW



A-147: UPPER BAY WINDOW GROUP AT EAST SIDE, CENTRAL QUADRANT



A-148: VIEW OF TRIM ADJACENT TO WINDOW CORNER



A-149: DENT IN ACCESSORY GROOVE ALONG LEFT SIDE OF WINDOW



A-150: LOWER LEFT CORNER OF WINDOW



A-151: VIEW ALONG LEFT SIDE, INDENTATION IN ACCESSORY GROOVE




A-152: LOWER RIGHT CORNER OF WINDOW, SOUTHEAST FACING



A-153: CENTER EAST WINDOW, VIEW OF LOWER RIGHT CORNER



A-154: VIEW TOWARDS LEFT CORNER AT CENTER EAST WINDOW ABOVE DOOR



A-155: SCRAPING ALONG EDGE OF BOTTOM WINDOW FRAME



A-156: ADJACENT AREA ALONG BOTTOM WINDOW FRAME, DENT WITH SCRAPE MARKS



A-157: NORTHEAST FACING WINDOW AT CENTER BAY PROJECTION



A-158: LOWER LEFT CORNER OF WINDOW



A-159: VIEW OF SASH, DENT WITH SCRAPE MARK PRESENT



A-160: LOWER DENT ALONG LEFT SIDE OF SASH, MARKS VISIBLE



A-161: UPPER EAST WINDOW ABOVE PORCH



A-162: VIEW OF DENT ALONG BOTTOM ACCESSORY GROOVE



A-163: DENT IN LEFT SIDE ALONG ACCESSORY GROOVE



A-164: SOUTH DOOR, SOUTHEAST WINDOW AT PORCH



A-165: DENT WITH MISSING FINISHES ALONG BOTTOM OF WINDOW



A-166: DENT WITH SCRAPE MARK AT LEFT SIDE OF SASH



A-167: EAST AND NORTHEAST FACING WINDOWS AT PORCH



A-168: LOWER RIGHT CORNER OF EAST PICTURE WINDOW



A-169: BOTTOM SASH, SEALANT VISIBLE ALONG GLAZING



A-170: VIEW OF DRIP CAP ALONG TOP OF WINDOW



A-171: UPPER RIGHT CORNER OF WINDOW




A-172: ADJACENT AREA ALONG DRIP CAP, OUTER EDGE UNEVEN



A-173: LOWER PORTION OF NORTHEAST FACING WINDOW



A-174: UPWARD DENT ALONG BOTTOM ACCESSORY GROOVE



A-175: SCRAPE MARKS AT RIGHT SIDE FRAME



A-176: NORTH FACING WINDOW GROUP AT REAR PORCH



A-177: VIEW OF BASE OF LEFT MULLION



A-178: LOWER LEFT CORNER OF WINDOW GROUP



A-179: VERTICALLY ALIGNED DENTS AT LEFT SASH



A-180: VIEW ALONG BOTTOM OF SASH, SCRAPE PRESENT



A-181: VIEW OF MULLION CAP AT LEFT MULLION OF WINDOW



A-182: RIGHT MULLION AT NORTH FACING PORCH WINDOW



A-183: UPWARD DENT IN ACCESSORY GROOVE AT FRAME



A-184: NORTH AND EAST FACING WINDOWS AT CORNER OF KITCHEN



A-185: EAST WINDOW, RIGHT SIDE, DENT WITH SCRAPE MARK



A-186: VIEW OF LOWER CORNER OF UPPER WINDOW AT EAST WALL



A-187: VENTS IN EAST WALL



A-188: NO DENTS VISIBLE IN SURFACE OF VENT



A-189: VIEW OF ADJACENT VENT HOOD



A-190: LOWER RIGHT CORNER OF NORTH KITCHEN WINDOW



A-191: CAULKING AT LOWER RIGHT CORNER



A-192: LOWER LEFT CORNER OF WINDOW




A-193: SCRAPE ALONG LEFT SASH NEAR CORNER



A-194: VIEW BETWEEN UPPER AND LOWER WINDOW AT NORTH KITCHEN WALL



A-195: LEFT SIDE BETWEEN UPPER AND LOWER NORTH KITCHEN WINDOWS



A-196: MAIN LEVEL WINDOW, EAST SIDE AT NORTH QUADRANT



A-197: VIEW ALONG TOP OF WINDOW



A-198: LOWER LEFT CORNER OF WINDOW



A-199: SCRAPE MARKS ALONG OUTER EDGE OF LOWER FRAME



A-200: LEFT SIDE, DENT IN ACCESSORY GROOVE



A-201: SCRAPE MARK WITH DAMAGE TO FINISHES AT BOTTOM FRAME



A-202: VIEW OF CAULKING AT MULLION



A-203: ADJACENT MULLION SHOWING CAULKING



A-204: LOWER RIGHT CORNER OF WINDOW



A-205: UPPER LEVEL NORTH FACING WINDOW ABOVE KITCHEN



A-206: LOWER LEFT CORNER, DENT IN ACCESSORY GROOVE



A-207: UPPER EAST BEDROOM WINDOW GROUP AT NORTH QUADRANT



A-208: AREA OF SIDING PENETRATION BELOW WINDOW



A-209: VIEW ALONG BOTTOM OF WINDOW NEAR MULLION



A-210: VIEW NORTH ALONG BOTTOM SASH OF RIGHT CASEMENT



A-211: AREA OF MULLION AT UPPER BEDROOM WINDOW



A-212: VIEW OF SIDING PENETRATION FROM LADDER



A-213: WINDOW AT REAR/EAST SIDE OF GARAGE



A-214: LOWER LEFT CORNER, SCRAPE MARKS IN ACCESSORY GROOVE



A-215: LEFT SIDE OF WINDOW AT GARAGE



A-216: LOWER RIGHT CORNER OF GARAGE WINDOW



A-217: VIEW OF MULLION AT GARAGE WINDOW