

PAYMENT RECEIPT**18393**

NAME MIKE WILER			REPAIR ORDER 18393
ADDRESS			HOME PHONE (360)813-1750
CITY	STATE	ZIP	WORK PHONE
EST. COMPLETION DATE			

**MAACO COLLISION REPAIR
& AUTO PAINTING**

CENTER: M1637
911 UNION AVE.
BREMERTON, WA 98312
TEL: (360)373-0577 FAX: (360)373-0881

ESTIMATE DATE 06/27/2007
ESTIMATOR 07

YEAR/MAKE/MODEL 1971 PLYMOUTH SCAMP			
LICENSE/STOCK NO.	STATE	VIN	
DATE IN 07/02/2007	DATE OUT 07/04/2007	☐ INS	☐ TRADE & FLEET
PAINT COLOR: ORANGE		☐ WARRANTY	
MILEAGE IN:		OUT:	

Total Sales(Incl. Tax)	2094.57
Total Payments	- 2094.57
Balance Due	0.00

Date	Type	Amount Paid
06/27/2007	Cash	100.00
07/06/2007	Credit Card	1994.57
		2094.57

COMPLETION CERTIFICATE

I HAVE INSPECTED MY VEHICLE AND AM SATISFIED THAT THIS SHOP HAS COMPLETED THE SERVICES ON THE REPAIR ORDER REFERENCED ABOVE. I HAVE ALSO RECEIVED A COPY OF THIS REPAIR ORDER AND THE WARRANTY REGISTRATION CARD.

X**PAYMENT INFORMATION****DEPOSITS/PAYMENT**

DATE _____ REC'D BY _____

METHOD OF PAYMENT

CASH ☐
CHECK ☐
CREDIT CARD ☐

TOTAL INCL. TAX

DEPOSITS/PAYMENT

BALANCE

PAYMENTS

DATE _____ REC'D BY _____

CASH ☐
CHECK ☐
CREDIT CARD ☐

PAYMENT

BALANCE

