Report

S/s Name:	Substation1	**Unit Affected:**	750 MVA TR.3	**History:**	---			
Indication	Winding Temperature/Oil Temperature		**OLTC Condition**	**Parallel**	**Ind.**	**Master**	**Follower**	
				✓	✓	✓	✓	
Action Taken	Replaced	**Visual Check**	Cooling System ✓ Breather ✓ Surrounding Condition ✓ Leaks ✓ Oil Level ✓ Cable Boxes ✓	**STATUS**	**Clear**			
Incident date/time	03-05-2026 , 12:00 PM		**If wire Isolated**	**Location**	---			
Work finish time	02:00 PM			**Reason**	---			
NOTES	notesss			**Isolated device Info**	---			
			Eng Name	Anoop S		**Signature**	---	
			Section Head Signature	---				