

DAILY DRILLING & INCIDENT REPORT

Date: 2024-10-14

Operator: GeoMind Energy Corp

Well Information

Well ID: GEO-DEEP-09

Latitude: 28.5356

Longitude: 77.1242

Current Depth: 3250.5 m

Target Formation: Lower Barail Sandstone

Incident Details

Event Type: Severe Mud Loss

Time of Incident: 14:30 hrs

Event Depth: 3110.0 m

Formation: Fractured Limestone

Description of Event:

While drilling ahead at 3110.0m, the rig experienced a total loss of mud circulation. Suspect encountered a highly fractured limestone zone. Pumped 100 bbls of Loss Circulation Material (LCM) pill. Waited on LCM to cure. Circulation partially regained after 4 hours.

NPT (Non-Productive Time) Tracking

NPT Duration: 240 mins

NPT Category: Fluid Loss

Underground Infrastructure Survey

Warning: Seismic scans indicate a pre-existing high-pressure water Aquifer nearby.

Infrastructure ID: AQ-774-B

Infrastructure Lat: 28.5360

Infrastructure Long: 77.1250

Depth: 3150.0 m

Type: Aquifer