

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Review and Update — Summary of Key Findings

Property: Silo Mills Phases I–IV, Burleson / Cleburne, Johnson County, Texas

Approximate Acreage: Approximately 830 acres

Site Inspection Date: October 8, 2020

Report Date: October 25, 2020

Environmental Firm: **TBK Environmental**

EXECUTIVE SUMMARY

TBK Environmental conducted a Phase I Environmental Site Assessment Review and Update of the approximately 830-acre Silo Mills development in Johnson County, Texas. The review, commissioned by Silo Mills Investment I LLC in connection with financing through Bank OZK, consisted of an updated site inspection, refreshed regulatory database review, and review of the prior 2018 Phase I ESA.

CONCLUSION: This assessment has not revealed any significant known or suspect recognized environmental conditions associated with the subject property. No further study of the subject site is deemed necessary.

KEY FINDINGS

-
- No significant known or suspect recognized environmental conditions (RECs) identified in connection with the subject property.
 - No Chemicals of Concern identified anywhere on the property.
 - Historical landfarm operations reviewed via regulatory database — all permitted levels followed; deemed not a concern.
 - No new permits or enforcement actions identified against the site.
 - Vapor Encroachment Screening determined not necessary.
 - No unusual odors, standing water, or evidence of releases observed during inspection.

SITE OBSERVATIONS

A physical site inspection was conducted on October 8, 2020. The property consisted of vacant land with eight natural gas well pads that appeared active at the time of inspection. No visible signs of significant environmental impact were observed; vegetation included overgrown landscaping with no signs of damage and only minor debris. No groundwater monitoring, recovery, or water wells were present. No unusual odors, standing water, chemical spills, or releases were observed.

FORMER LANDFARM — HISTORICAL RECORD REVIEW

Federal and state regulatory database review (Envirosearch Corporation) identified the property on account of permitting required to treat water-based drilling fluids and the closure process for each cell. TBK confirmed landfarm operations were conducted under proper state regulatory permits, all permitted levels were followed, and no enforcement actions were present — deemed not a concern in connection with the subject property.

ASSESSOR STATEMENT

“This assessment has not revealed any significant known or suspect recognized environmental conditions associated with the subject property. TBK concludes, based on the supporting evidence discovered during this review, that no further study of the subject site is deemed necessary.”

— TBK Environmental

This document is a summary of the full Phase I Environmental Site Assessment Review and Update report dated October 25, 2020, prepared by TBK Environmental.