



Virtual Inspections & Claims

Customer Details

- **Customer Name:** Bill Kinman
- **Customer ID:** 235-53-425891
- **Phone Number:** 8473469560

Inspection Summary

Exported on May 8, 2019

- **Inspection Started:** 12:41:29PM EDT on 05/08/2019
- **Total Photos Uploaded:** 10 photos uploaded
- **Total Photos Passed Verification:** 9 of 10 photos passed verification

Customer Address: ● Bridgepointe Parkway, San Mateo, CA, USA




Photo Index

9 of 10 photos passed verification






Photo 1

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A


Verified Metadata & Sensor Information

- **Server Time:** 1:02:28PM EDT on 05/08/2019
- **Device Time:** 1:02:28PM EDT on 05/08/2019
- **Geo:** 34.10369162916588, -118.2935782616197
- **Accuracy:** 5 meters
- **Device Make and Model:** Apple iPhone X

Photo 2

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A


Verified Metadata & Sensor Information

- **Server Time:** 1:02:07PM EDT on 05/08/2019
- **Device Time:** 1:02:07PM EDT on 05/08/2019
- **Geo:** 34.10367287959621, -118.29359916823785
- **Accuracy:** 65 meters
- **Device Make and Model:** Apple iPhone X

Photo 3

Photo Details

✓	✓	✓	✓	!	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A

Verified Metadata & Sensor Information

• Server Time:	12:47:24PM EDT on 05/08/2019
• Device Time:	12:47:23PM EDT on 05/08/2019
• Geo:	34.10363429694819, -118.29368228103806
• Accuracy:	10 meters
• Device Make and Model:	Apple iPhone X

Flagged Results

○ Image Analysis




Using a series of image forensics tests, ensures that the image was not re-captured from a pre-existing photo on a screen.

The image was too blurry or distorted to be tested for picture of picture. It should be manually reviewed.

Photo 4

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A


Verified Metadata & Sensor Information

- **Server Time:** 12:47:14PM EDT on 05/08/2019
- **Device Time:** 12:47:14PM EDT on 05/08/2019
- **Geo:** 34.10369741267907, -118.2936884836464
- **Accuracy:** 10 meters
- **Device Make and Model:** Apple iPhone X

Photo 5

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A



Verified Metadata & Sensor Information

Server Time:	12:46:52PM EDT on 05/08/2019
Device Time:	12:46:52PM EDT on 05/08/2019
Geo:	34.10371379929977, -118.29384505759765
Accuracy:	10 meters
Device Make and Model:	Apple iPhone X

Photo 6

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A


Verified Metadata & Sensor Information

• Server Time:	12:46:28PM EDT on 05/08/2019
• Device Time:	12:46:28PM EDT on 05/08/2019
• Geo:	34.10365349150645, -118.29391848306943
• Accuracy:	30 meters
• Device Make and Model:	Apple iPhone X

Photo 7

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A


Verified Metadata & Sensor Information

Server Time:	12:46:19PM EDT on 05/08/2019
Device Time:	12:46:19PM EDT on 05/08/2019
Geo:	34.10360906741964, -118.29394388023604
Accuracy:	30 meters
Device Make and Model:	Apple iPhone X

Photo 8

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A



Verified Metadata & Sensor Information

• Server Time:	12:45:15PM EDT on 05/08/2019
• Device Time:	12:45:15PM EDT on 05/08/2019
• Geo:	34.10375654700594, -118.29370080504407
• Accuracy:	10 meters
• Device Make and Model:	Apple iPhone X

Photo 9

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

Lamp

Internal Note

N/A



Verified Metadata & Sensor Information

• Server Time:	12:44:58PM EDT on 05/08/2019
• Device Time:	12:44:58PM EDT on 05/08/2019
• Geo:	34.103723145121805, -118.29372913587679
• Accuracy:	10 meters
• Device Make and Model:	Apple iPhone X

Photo 10

Photo Details

✓	✓	✓	✓	✓	✓	✓
Device Integrity	Data Transfer	Time & Date	Location	Image Analysis	Image Search	Blockchain



Customer Note

N/A

Internal Note

N/A

Verified Metadata & Sensor Information

- **Server Time:** 12:44:46PM EDT on 05/08/2019
- **Device Time:** 12:44:46PM EDT on 05/08/2019
- **Geo:** 34.10372741989242, -118.29378160659064
- **Accuracy:** 10 meters
- **Device Make and Model:** Apple iPhone X

Inspection Timeline

● Ready for Review

- **08 May 2019** 12:41pm EDT
Event created byÂ **Lauren Sandberg**
- **08 May 2019** 12:41pm EDT
Initial text message with app link sent byÂ **Lauren Sandberg**
- **08 May 2019** 12:41pm EDT
Text message received
- **08 May 2019** 12:44pm EDT
Customer clicked link to app store
- **08 May 2019** 12:45pm EDT
Photo passed verification
New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:45pm EDT
Photo passed verification
New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:45pm EDT
Customer Note updated:
Lamp
- **08 May 2019** 12:46pm EDT
Photo passed verification
New photo uploaded from 1809 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:47pm EDT
Photo passed verification
New photo uploaded from 1765 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:47pm EDT
Photo passed verification
New photo uploaded from 1806 N Berendo St, Los Angeles, CA 90027

- **08 May 2019** 12:47pm EDT

Photo passed verification

New photo uploaded from 1765 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:48pm EDT

Photo passed verification

New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:48pm EDT

Photo verification warning

New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 12:48pm EDT

Customer marked the event as finished
- **08 May 2019** 1:00pm EDT

Request for more photos sent by **Lauren Sandberg**

Please take more photos of the documentation.
- **08 May 2019** 1:00pm EDT

Text message received
- **08 May 2019** 1:02pm EDT

Customer marked the event as finished
- **08 May 2019** 1:02pm EDT

Photo passed verification

New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027
- **08 May 2019** 1:03pm EDT

Photo passed verification

New photo uploaded from 1801 N New Hampshire Ave, Los Angeles, CA 90027