Tenuli Auto Care

Vehicle Repairs, Painting & Rent a Car

No-172/1-B, Keselwathugoda, Yakkala.
0715882903 | tenulicabsautocare@gmail.com

REPAIR COMPLETION & FINAL BILL

LKR

DOCUMENT NO.	JOB NO.	ISSUED · SRI LANKA TIME	REVISION
SAMPLE-FINAL-001	TAC-JOB-3	25 Oct 2026, 14:30	2

Estimate: **TAC-EST-3** Received: **1 Jan 2026, 08:00** Completed: **25 Oct 2026, 14:30**
Original document: TAC-INV-2 · 25 Oct 2026

SAMPLE / TEST DATA — NOT A CUSTOMER BILL

CUSTOMER DETAILS

SAMPLE CUSTOMER

0700000000

VEHICLE DETAILS

TEST-118

SAMPLE vehicle

REPORTED PROBLEM

Damage to the vehicle body.

REQUESTED REPAIRS / SERVICES

Repair and paint damaged body panels.

No.	Description / service / part	Pos.	Qty	Unit price	Discount	Amount
	REPLACEMENT ITEMS					
1	Front bumper replacement	Front	1	70,000.00	0.00	**70,000.00**
	REMOVAL & REFITTING ITEMS					
2	Remove and refit body panels	Front	1	10,000.00	0.00	**10,000.00**
	REPAIR ITEMS					
3	Body panel repair	Front	1	10,000.00	0.00	**10,000.00**
	PAINT ITEMS					
4	Prepare and paint repaired panels	Front	1	10,000.00	0.00	**10,000.00**

COMPLETED WORK

Recorded repairs completed.

RECORDED PAYMENTS

25 Oct 2026, 14:30 · Advance · Bank transfer · TEST-ADVANCE	**LKR 20,000.00**
25 Oct 2026, 14:30 · Payment · Cash	**LKR 30,000.00**
25 Oct 2026, 14:30 · Payment · Cash	**LKR 50,000.00**

PAYMENT SUMMARY

Paid

Captured at: 25 Oct 2026, 14:30
This bill records completed repairs and payments at issue. Vehicle handover is recorded separately.

Final bill total	**LKR 100,000.00**
Advance payments applied	LKR 20,000.00
Subsequent payments applied	LKR 80,000.00
Total net payments applied	LKR 100,000.00
Balance due	**LKR 0.00**

SAMPLE OPERATOR

Prepared by | Authorised signature | Customer signature - bill received