# Damage photos - VW Golf VIII

Taken by the customer · 06 Nov 2026




Photo 1: Rear bumper, dent left of centre




Photo 2: Rear light left, cracked lens

*SYNTHETIC DEMO DOCUMENT - generated for the Clearpath hackathon prototype. Not a real record.*