Damage photos - KS FT 2026

Taken by the customer · 06 Nov 2026



Photo 1: Rear bumper, dent left of centre



Photo 2: Rear light left, cracked lens

SYNTHETIC DEMO DOCUMENT - generated for the Clearpath hackathon prototype. Not a real record.