

01/26/77

TWO LEVEL - BRICK VENEER W/ WOOD SIDING & TRIM
LOT SLOPES FRONT TO BACK

NO VISIBLE STRESS CRACKS AT
VISIBLE PORTION OF MAIN HOUSE FDN
ONE STRESS CRACK AT BACK PORCH
FDN

