


# Condition of Structures in Bloomfield



Maxar, Microsoft, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, (c) OpenStreetMap contributors, and the GIS User Community



- |                       |                      |                  |
|-----------------------|----------------------|------------------|
| Worn-Out              | Badly Worn - Average | Good             |
| Worn-Out - Badly Worn | Average              | Good - Very Good |
| Badly Worn            | Average - Good       |                  |

