Island Utility Construction
6129 Scott Road,
Duncan, BC
V9L 6Y8
250 715 0539

# DVI Trailer 05 36158U 2007 Interstate Load Runner Box

## Information

Shop

Island Office

Friday, March 20th 2026, 8:09 AM (PDT -07:00)

## General

| | |
|---|---|
| Location Of Inspection | **Shop** |

**Trailer 05 36158U 2007 Interstate Load Runner Box**

**Truck Used**

Truck 01 - 2016 Ford F150 Crew Cab PR5368

- ✓ ✗ NA Registration & Insurance
- ✓ ✗ NA CVI & Decal

## Stationary Check

- ✓ ✗ NA Tires & Rims
- ✓ ✗ NA Trailer Body - Fenders, Deck, Bumper, Tongue, Coupler, Ramp & Door
- ✓ ✗ NA Doors Secured
- ✓ ✗ NA Load Secured, No Debris Or Loose Objects
- ✓ ✗ NA Truck Hitch Pinned & Keeper Installed
- ✓ ✗ NA Hitch Ball Correct Size, Captured Securely In Coupler
- ✓ ✗ NA Coupler Latched & Pinned
- ✓ ✗ NA Chains Crossed & Connected, Gates Present & Operable
- ✓ ✗ NA Electrical Connector Secured
- ✓ ✗ NA Running & Marker Lights
- ✓ ✗ NA Turn Signals & Hazard Lights
- ✓ ✗ NA Brake Lights

## Breakaway Test

**If any of these tests fail, do not drive - park and chock the trailer securely, and inform your supervisor.**

Gain Up Tug Test From Standstill

Gain Up Roll Test

Electrical Disconnected, Breakaway Pin Pulled From Standstill

## Sign Off

Remarks

No Response

Defects?

Details of Defects:

No Response

| | |
|---|---|
| Inspector | **Mollie Corbett** |
| Driver | **Mollie Corbett** |

Uploaded photos of front & both back corners showing sides

| | |
|---|---|
| Photo Example | fbfb48a9-c813-4bbe-8038-8284dde87d0f |

I declare that the vehicle shown above has been inspected in accordance with the applicable requirements and any known issues have been noted above. Do not operate a vehicle and/or its contents if it is not safe to operate.

## Additional Photos

## Signatures

**Mollie Corbett,** *Maintenance Landscaper*

March 20th 2026, 8:09 AM (PDT -07:00)

48.7928786, -123.7454812