



Laser-Induced Damage Threshold Test (LIDT) Report

According to ISO 21254
No. LIDT-2026-004-ABC123

HiLASE

Prepared by: Msc. Fauzul Rizal (fauzul.rizal@hilase.cz)
Approved by: Mihai-George Mureşan, Ph.D. (mihai@hilase.cz)
Institute: HiLASE Centre, Institute of Physics ASCR
Address: Za Radnici 828, 252 41 Dolni Brezany, Czech Republic

Customer

Name: ABC Company
Sample ID: ABC123
Address: ABC Street, 123, Fairytale
Contact: John Doe

1. Report Identification

Report Number: LIDT-2026-004-ABC123

Issue Date: 07 July 2026

2. Sample Information

Sample ID: ABC123

Description: ABC Sample

Date Received: 07 July 2026

Preparation:

3. Laser and Environmental Conditions

Laser Type:

Wavelength (nm): 1030

Repetition Frequency: 1 kHz or 10 kHz

Output Energy/Power: 10 mJ or 1 mJ

Pulse Duration (1/e²): 1.2 ps

Effective Pulse Duration:

Polarization: Linear

Beam Diameter (1/e²): 7.5 mm

Beam Profile (Near Field):

Beam Delivery:

4. Test Identification

Procedure:

Objective:

Sites / Pulses per Site:

Damage Detection:

5. Test and Procedure Specification

Environment: Standard laboratory, 22.0 °C, 40%

Vacuum: No

Focusing System: Spherical lens, f = 500 mm

Beam Energy Management: Attenuator (polarization-based, motorized)

Sample Position: In focus

Spatial Beam Shape: , ellipticity = N/A%

Measured Beam Surface: N/A

Gaussian Fit Beam Diameter: N/A

6. Error Budget

Pulse-to-pulse energy stability: $\pm 5\%$
Pulse-to-pulse spatial profile stability: $\pm 12\%$
Pulse-to-pulse temporal stability: $< 1\%$
Energy monitor calibration: $\pm N/A\%$
Energy monitor accuracy: N/A μJ
Beam profiler accuracy: 3.45 μm
Beam profiler calibration: $\pm \text{None}\%$

7. Test Results

Sample dimensions:
Tested aperture:
Test site size:
Number of test sites: 1
Test sites distance (center-center):
Test site matrix: Circular
Test type: 1-on-1
Pulses per site:
Pulses total:
Online damage detection: Online camera
Offline damage detection: Laser scanning microscope