

The image classified as: Contains Crack  
Length: 5.86 cm  
Width: 0.88 mm  
Orientation: horizontal  
Positive Crack Probability: 72.96%  
Negative Crack Probability: 27.04%  
Location of Crack: None  
Crack Type: None  
Crack Progression: None  
Date Added: 2023-04-06 22:10:39

