

The image classified  
as: Contains Crack  
Length: 47.26 cm  
Width: 2.37 mm  
Orientation: vertical  
Positive Crack  
Probability: 73.11%  
Negative Crack  
Probability: 26.89%

