



The image characterized as: **Contains Crack**

Length: 6.03 cm

Width: **1.14 mm**

Positive Crack Probability: 73.11%

Negative Crack Probability: 26.89%

Location of Crack: Column

Name of Project: **test**

Name of Folder: **test folder**

Date Added: 2023-05-11 02:35:36

Remarks: