

The image classified as: Contains Crack

Length: 58.97 cm

Width: 98.56 mm

Orientation: None

Positive Crack Probability: 73.11%

Negative Crack Probability:

26.89%

