

The image classified as: Contains Crack

Length: 43.22 cm

Width: 2.19 mm

Orientation: None

Positive Crack Probability: 73.11%

Negative Crack Probability:

26.89%

