

WATER QUALITY COMPLIANCE REPORT

Sedona Water System

Serving Sedona — Yavapai County, Arizona

Report Period	Q1 2026 (Jan–Mar)	Compliance Status	COMPLIANT
---------------	-------------------	-------------------	-----------

1. Executive Summary

During the Q1 2026 (Jan–Mar) monitoring period, the Sedona water system met all applicable federal and state drinking water standards under the Safe Drinking Water Act. All sampled contaminant levels remained within EPA Maximum Contaminant Levels (MCLs). The system served its Yavapai County communities without any quality exceedance requiring public notification.

2. Contaminant Monitoring Results

Parameter	Result	EPA Limit	Status
Turbidity (NTU)	0.3	< 0.5	PASS
Lead (ppb)	0.01	≤ 15	PASS
Copper (ppm)	0.12	≤ 1.3	PASS
Chlorine Residual (ppm)	0.9	0.2 – 4.0	PASS
pH	7.8	6.5 – 8.5	PASS
Total Dissolved Solids (ppm)	280	≤ 500	PASS
Total Coliform Bacteria	Absent	Absent	PASS

3. Sampling Methodology

Samples were collected from representative points across the Sedona distribution network in accordance with 40 CFR Part 141. Turbidity was measured continuously via inline nephelometric sensors with grab-sample confirmation. Lead and copper were sampled at high-risk service connections following the Lead and Copper Rule protocol. All laboratory analyses were performed by an Arizona Department of Health Services certified laboratory.

4. Continued Monitoring

The Sedona system will continue its routine monitoring schedule. Quarterly contaminant sampling and continuous turbidity monitoring remain in effect. No corrective action is required at this time.

Prepared by the Arizona Water Company Water Quality Division. This document constitutes a regulatory filing under the Safe Drinking Water Act and contains operational compliance data classified as Company Confidential. Reviewed by: Dr. Susan Park, Water Quality Manager.