

# ASSET PROFILE

Asset Tag: CONE-03082018-DT1

## ASSET DETAILS

**Category:** Construction Equipment**ID:** DT1**Name:** DUMPTRUCK**Model:** CXZ19J-3005460**Make/Brand:** ISUZU**Owner Company:** PULSAR CONSTRUCTION**Date Acquired:** 2/7/2012**Acquisition Cost:** 1,200,000.00**Plate No:** FGR-254**Engine No:** 10PC1-970126**Warranty Date:** 01/01/2018**Location:** Quarry**Assigned to:** Erik Subnet**Status:** Active

## CURRENT OPERATING RECORD

Operating Hours 12,345

Kilometers Traveled 71,234

Loads (m3) 71,234

Diesel (L) Consumed 55,123

Gas (L) Consumed 90,123

Oil (L) Consumed 23,123

## INSURANCE

Insurance Co.	Description	Contact Person	Start Date	End Date
BPI	Comprehensive Insurance	Jerik Erikson	12/12/2012	12/12/2025
BPI	Insurance Description	Mykee Caparas	12/12/2015	12/12/2020

## MAINTENANCE HISTORY

Control#	JO Date	Date Started	Date Completed	Conducted By
JO-03122018-1	03/12/2018	03/15/2018	03/16/2018	Jungle Repair

Control#	JO Date	Date Started	Date Completed	Conducted By
JO-03122018-2	03/12/2018	03/15/2018	03/16/2018	Jungle Repair
JO-03122018-1	03/12/2018	03/15/2018	03/16/2018	Jungle Repair
JO-03122018-2	03/12/2018	03/15/2018	03/16/2018	Jungle Repair
JO-03122018-2	03/12/2018	03/15/2018	03/16/2018	Jungle Repair

## EVENTS

Status	Event Date	Description/Remarks
MAINTENANCE	Date 02/16/2018	Dumptruck Preventive Maintenance of engine
LEASE	Date 02/16/2018	Dumptruck Preventive Maintenance of engine
DONATE	Date 02/16/2018	Description/Remarks
SELL	Date 02/16/2018	Description/Remarks
DISPOSE	Date 02/16/2018	Description/Remarks
LOST/MISSING	Date 02/16/2018	Description/Remarks

\* \* \* END OF ASSET PROFILE \* \* \*