

Incident Report for 5/18/2026 Environmental Incident (Incident ID: 5971)

☐ Initial ☒ Update ☐ Close Out

Incident Details				Reporting Party Details			
Description:	Brenna Tank Release 5/18	Incident Date and Time:	5/18/2026 11:50 AM	Reporting Party Name:	Scott Yount	Reporting Party Company:	Tallgrass Water North Dakota, LLC
Incident Type:	Environmental Incident	Incident Subtype :	Tank Overflow	Reporting Party Phone:		Reporting Party Email:	
Source Type:	Fixed Facility	Source Subtype:		Reported Date and Time:	5/19/2026 10:14 AM		
Incident Status:	Active	Released Into Medium :	Soil				
Site Details				Incident Location			
Is Spill Continuous:	No	Is Spill Contained:	Yes	Address:			
Discovered/Start Date and Time:	5/18/2026 11:50 AM	End Date and Time:	5/18/2026 12:00 PM	Location Description:			
Reported to NRC:	No			Latitude: 47.9867324177452 Longitude: -102.899723532441			
Well Name :	BRENNA SWD 1	NDIC File Number :	90217	Section: 13 Township: 152 N			
Oil/Gas Operator :	Tallgrass Water North Dakota, LLC	Oil/Gas Field Name :	UNION CENTER	Range: 96 W Quarter: NE¼			
Company Name:	Tallgrass Water North Dakota, LLC	Facility Name:	Brenna SWD 1	Qquarter: SE¼ Source Water Protection Area:			
Facility Address:	none, none, ND 58847	Nature of Business:	Disposal of produced water via injection well	County/Tribe: McKenzie County Fire District: KEENE FIRE			
Extent of Spill/Release:	Confined to Property of Origin - Secondary Containment			Federal Property: No Trust Land: No			
Extent Details:	Release confined to line secondary containment, no impacts to onsite soil						
Incident Contacts							
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact			
Name:	Scott Yount	Name:	Scott Yount				
Title:	Sr EHS Specialist	Title:	Sr EHS Specialist				
Company Name:	Tallgrass Water North Dakota, LLC	Company Name:	Tallgrass Water North Dakota, LLC				
Company Address:	4992 SW Buffalo Road, Towanda, KS 67144, United States	Company Address:	4992 SW Buffalo Road, Towanda, KS 67144, United States				
Phone: 316-322-3514	24 Hr.Phone:	Phone: 316-322-3514	24 Hr.Phone:				
Email:	Mobile/Pager:	Email:	Mobile/Pager:				

Incident Report for 5/18/2026 Environmental Incident (ID: 5971)

Incident and Risks

Expected Cause of Fixed Facility Tank Overflow : Unknown

Weather : Light Rain

Distance from Nearest Occupied Building :

Distance from Nearest Water Well :

Known Health Risks : none

Nature of Locale where Incident Occurred : Oil and Gas Facilities

Wind Direction : calm

Wind Speed : calm

Number of Confirmed Injuries : 0

Number of Confirmed Fatalities : 0

Immediate Potential Threats (first 24 Hr) :

None of the Above: No immediate potential threats

Delayed Potential Threats (after first 24 hr) :

None of the Above: No delayed potential threats

Response Details

Estimated Clean Up Completion Date : 06/05/2026

Waste Disposal Location :

Protective Actions Taken : Facility was isolated to prevent the release of additional produced water/crude oil mixture.

Other Response Details :

Evacuations :

No Response Reason :

Shelter In Place :

Clean Up Action Taken : Vacuum truck was utilized to remove the produced water/crude oil mixture from the secondary containment. The lined containment was washed using a heated power washer (Hotsy). Then the containment was flooded with water with dawn to remove additional crude oil/produced water.

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Produced Water		No	No	90 bbl	90	0	90 bbl	90
N/A	Crude Oil		No	No	10 bbl	10	0	10 bbl	10

Incident Observations

Note Added Date	Incident Observations
5/19/2026	According to the incident report, produced water and crude oil were released at a salt water disposal facility and were confined to secondary containment. NDIC retains oversight.