

Incident Report for 5/20/2026 Oil/Gas Spill (Incident ID: 5976)
☒ Initial ☐ Update ☐ Close Out

Incident Details		Reporting Party Details		
Description: Clarks Creek Central, gasket on water transfer filter pod failed resulting in approximately 19Bbbls of produced water to be released both inside and outside of the containment but isolated to the location. CTB 220890 Incident Type: Oil/Gas Spill Incident Subtype : Equipment Failure Source Type: Fixed Facility Source Subtype: Incident Status: Active Released Into Medium : Soil		Reporting Party Name: Charles Miller Reporting Party Company: EOG Resources, Inc. Reporting Party Phone: Reporting Party Email: Reported Date and Time: 5/21/2026 5:48 AM		
Site Details		Incident Location		
Is Spill Continuous: No Is Spill Contained: No Discovered/Start Date and Time: 5/20/2026 04:17 PM End Date and Time: 5/20/2026 04:47 PM Reported to NRC: No Well Name : NDIC File Number : Oil/Gas Operator : Oil/Gas Field Name : Company Name: EOG Resources, Inc. Facility Name: CLARKS CREEK CPF 21 WELL PAD (Tier II Facility ID: 9505) Facility Address: McKenzie, Mandaree, ND 58757 Nature of Business: EP Extent of Spill/Release: Confined to Property of Origin Extent Details: Inside main tank containment where water transfer pumps and oil LACTs are. Out side of the main tank containment on the NW corner.		Address: Location Description: Latitude: 47.9058999999992 Longitude: -102.755399999998 Section: 7 Township: 151 N Range: 94 W Quarter: SE¼ Quarter: SE¼ Source Water Protection Area: County/Tribe: Three Affiliated Tribe Fire District: NEW TOWN FIRE Federal Property: No Trust Land: No		
Incident Contacts				
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact (Property Owner is Informed)
Name: Charles Miller Title: Sr. Environmental Rep Company Name: EOG Resources, Inc. Company Address: 6201 81st Ave NW., Stanley, ND 58784, United States Phone: 701-621-1813 24 Hr.Phone: Email: Mobile/Pager:		Name: Ross Talboom Title: Environmental Supervisor Company Name: EOG Resources, Inc. Company Address: 600 17th St, Suite 1000N, Denver, CO 80202, United States Phone: 303-565-9941 24 Hr.Phone: Email: Mobile/Pager:		Name: Company Name: Company Address: Phone: Email:

Incident Report for 5/20/2026 Oil/Gas Spill (ID: 5976)

Incident and Risks

Expected Cause of Fixed Facility Equipment Failure :	Equipment Failure/Malfunction	Nature of Locale where Incident Occurred : Oil and Gas Facilities	
Weather :	Clear/Sunny	Wind Direction :	Wind Speed :
Distance from Nearest Occupied Building :	1492 feet	Number of Confirmed Injuries :	0
Distance from Nearest Water Well :		Number of Confirmed Fatalities :	0
Known Health Risks :	N/A		
Immediate Potential Threats (first 24 Hr) :		Delayed Potential Threats (after first 24 hr) :	
None of the Above: N/A		None of the Above: N/A	

Response Details

Estimated Clean Up Completion Date :	06/11/2026	Waste Disposal Location :	TBD
Protective Actions Taken :	Filter Pod skid was shutdown and gasket was replaced.	Other Response Details :	
Evacuations :		No Response Reason :	N/A
Shelter In Place :			
Clean Up Action Taken :	Standing fluid was sucked up, loose impacted material outside of containment will be moved to inside containment. 811 Call will be placed and impacted material will be cleaned up with a Hydro-Vac		

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Produced Water		No	No	19 bbl	19	0	19 bbl	19

Incident Observations

Note Added Date	Incident Observations
5/21/2026	According to the incident report, this release was located on Three Affiliated Tribe land, MHA holds jurisdiction.