

Incident Report for 5/26/2026 Oil/Gas Spill (Incident ID: 5993)
☒ Initial ☐ Update ☐ Close Out

Incident Details		Reporting Party Details	
Description: A slow drip was observed coming from a body bleed valve on the Cenex Pipeline Block Valve 250, located just north of 19th Ave NW, approximately 6.5 miles northwest of Fargo. The employee who observed the drip immediately tightened the valve and stopped the drip and notified the EH&S department. The employee then removed the impacted soil with a shovel and placed it into 3, 5-gallon buckets for characterization and disposal. The employee estimated approximately 1 gallon had been released to the ground surface below the valve. The coordinates for the valve are 46.906537, -96.919163.	Incident Date and Time: 5/26/2026 12:00 PM	Reporting Party Name: Jake Hover Reporting Party Phone: Reported Date and Time: 5/27/2026 11:54 AM	Reporting Party Company: CHS Reporting Party Email:
Incident Type: Oil/Gas Spill Incident Subtype : Pipeline Leak Source Type: Pipeline Source Subtype: Distribution Pipeline Incident Status: Active Released Into Medium : Soil		Incident Location Address: Location Description: Latitude: 46.9065369999992 Longitude: -96.9191629999984 Section: 30 Township: 140 N Range: 49 W Quarter: SW¼ Qquarter: SE¼ Source Water Protection Area: West Fargo City of County/Tribe: Cass County Fire District: HARWOOD FIRE Federal Property: No Trust Land: No	
Site Details			
Is Spill Continuous: No Is Spill Contained: Yes Discovered/Start Date and Time: 5/26/2026 12:00 PM End Date and Time: 5/26/2026 12:15 PM Reported to NRC: No Well Name : NDIC File Number : Oil/Gas Operator : Oil/Gas Field Name : Extent of Spill/Release: Confined to Property of Origin Extent Details: Small area of soil directly below the valve was impacted.			
Incident Contacts			
Responsible Authority Contact		Responsible Authority Compliance Contact	
Name: Jake Hover Title: Environmental Engineer Company Name: CHS P&T	Name: Jake Hover Title: Environmental Engineer Company Name: CHS	Property Owner Contact (Property Owner is Informed) Name: Company Name:	

Incident Report for 5/26/2026 Oil/Gas Spill (ID: 5993)

Company Address:	803 US HWY 212 S, Laurel, MT 59044, United States
Phone: 406-647-2793	24 Hr.Phone:
Email:	Mobile/Pager:

Company Address:	803 US HWY 212 S, Laurel, MT 59044, United States
Phone: 406-647-2793	24 Hr.Phone:
Email:	Mobile/Pager:

Company Address:	
Phone:	
Email:	

Incident Report for 5/26/2026 Oil/Gas Spill (ID: 5993)

Incident and Risks

Expected Cause of Pipeline Pipeline Leak Equipment Failure/Malfunction, Weather :

Weather : Clear/Sunny

Distance from Nearest Occupied Building :

Distance from Nearest Water Well :

Known Health Risks : None

Immediate Potential Threats (first 24 Hr) :

None of the Above: No threats

Nature of Locale where Incident Occurred : Oil and Gas Facilities

Wind Direction : Wind Speed :

Number of Confirmed Injuries : 0

Number of Confirmed Fatalities : 0

Delayed Potential Threats (after first 24 hr) :

None of the Above: No threats

Response Details

Estimated Clean Up Completion Date : 05/26/2026

Protective Actions Taken : Block valve area is fenced off and access is denied to any non-responding personnel. Bleed valve was closed and is no longer dripping.

Evacuations :

Shelter In Place :

Clean Up Action Taken : Soil below the valve was excavated and containerized for later disposal.

Waste Disposal Location : TBD

Other Response Details :

No Response Reason :

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Diesel		No	No	1 gal	0.02	5.83	1 gal	0.02

Incident Observations

Note Added Date	Incident Observations
5/27/2026	According to the incident report, diesel was spilled. Follow-up is necessary.