REPORT CONTAMINACIÓN

nº: 81529

FACILITY NAME: Lower Melville Wood Landfill, By Ladybank 81530

FacilityInspireID: UK.SEPA/200000095.Facility

COUNTRY: United Kingdom CONTINENT: EUROPE

CITY: Cupar, Fife

EPRTRSectorCode: 5 **eprtrSectorName:** Waste and wastewater management

MainActivityCode: 5(d)

targetRealase: AIR pollutant: Methane (CH4)

emissions: 602000

DAY: 27 **MONTH:** 10 **YEAR:** 2019

METEOROLOGICAL CONDITIONS

max_wind_speed: 1,37E+16 min_wind_speed: 2,25E+16 avg_wind_speed: 1,47E+16

max_temp: 9,6E+15 **min_temp:** 1,25E+16 **avg_temp:** 9,19E+15

DAYS FOG: 9

REPORTER NAME Brenda Holland

CITY_ID d784f55b1d1ae261dff896b5030ca94e