

REPORT CONTAMINACIÓN

FACILITY NAME: Millerhill Recycling & Energy Recovery Centre **nº:** 81596
FacilityInspireID: UK.SEPA/200002651.Facility **81597**

COUNTRY: United Kingdom **CONTINENT:** EUROPE
CITY: Millerhill, Dalkeith

EPTRSectorCode: 5 **eptrSectorName:** Waste and wastewater management

MainActivityCode: 5(b)

targetRelease: AIR **pollutant:** Carbon dioxide (CO2)
emissions: 1,32E+08

DAY: 4 **MONTH:** 12 **YEAR:** 2019

METEOROLOGICAL CONDITIONS

max_wind_speed: 2,09E+15 **min_wind_speed:** 2,46E+16 **avg_wind_speed:** 2,07E+15

max_temp: 5,74E+15 **min_temp:** 9,42E+15 **avg_temp:** 7,31E+15

DAYS FOG: 6

REPORTER NAME Jason Moses

CITY_ID c662b4b4d859a9c224b5ac0acf221748