

**REPORT CONTAMINACIÓN**

nº: 81539

**FACILITY NAME:** Avondale Landfill Site, Polmont

81540

**FacilityInspireID:** UK.SEPA/200000115.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Polmont**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(d)**targetRelease:** AIR **pollutant:** Nitrogen oxides (NOX)**emissions:** 101000**DAY:** 13 **MONTH:** 11 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,73E+16 **min\_wind\_speed:** 1,87E+16 **avg\_wind\_speed:** 1,65E+16**max\_temp:** 9,37E+15 **min\_temp:** 1,12E+16 **avg\_temp:** -2E+16**DAYS FOG:** 7**REPORTER NAME** Hunter Davidson**CITY\_ID** 941b15d27183b05e8e58e0fbc509e963