

**REPORT CONTAMINACIÓN**

nº: 81589

**FACILITY NAME:** Markinch Biomass CHP  
**FacilityInspireID:** UK.SEPA/200002509.Facility

81590

**COUNTRY:** United Kingdom  
**CITY:** Glenrothes

**CONTINENT:** EUROPE

**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management

**MainActivityCode:** 5(b)

**targetRelease:** AIR **pollutant:** Carbon dioxide (CO2)  
**emissions:** 4,87E+08

**DAY:** 4 **MONTH:** 9 **YEAR:** 2019

**METEOROLOGICAL CONDITIONS**

**max\_wind\_speed:** 8,03E+15 **min\_wind\_speed:** 2,01E+15 **avg\_wind\_speed:** 1,4E+15

**max\_temp:** 1,2E+16 **min\_temp:** 3,64E+16 **avg\_temp:** 5,76E+15

**DAYS FOG:** 13

**REPORTER NAME** Christian Winters

**CITY\_ID** 007e670e3bc4ccd47d59d8c578e751cb